




October 2023




North America


 **Canada 31 October 2023:** Ford is recalling 13,917 units of 2020-2023 Ford Mustang vehicles because a software problem could cause the low brake fluid warning lamp not to turn on if the brake fluid level gets too low - **crash risk**.

 **United States 31 October 2023:** Triumph Motorcycles America Ltd is recalling 3,557 units of 2020 Rocket 3 TFC, 2020-2024 Rocket 3 R, Rocket 3 GT, 2022 Rocket 3 GT Triple Black and Rocket 3 R Black motorcycles because the rear brake master cylinder may fail to move fluid through the system properly, requiring an extended distance to stop - **crash risk**.

 **United States 31 October 2023:** Toyo Tire Holdings of Americas Inc. is recalling 14,194 units


of Open Country and Extensa tires because they may have been produced using the wrong mold which can result in the tread or tire sidewall detaching - **crash risk**.


 **United States 31 October 2023:** Mack Trucks Inc. is recalling 12 units of 2024 Granite and TerraPro vehicles because the rear lifting bracket that attaches to the engine cylinder head may be insufficiently secured which can allow it to detach - **injury risk**.


 **Canada 30 October 2023:** Alliance RV is recalling 212 units of 2021-2023 Alliance RV Paradigm and Valor RV trailers because a wire connector for the solar panel could loosen and cause the wiring to overheat - **fire risk**.


 **United States 30 October 2023:** Chinook Motor Coach LLC is recalling 73 units of 2022-


2024 Bayside motorhomes because the rearview camera, or 360-degree view camera if equipped, may not display a rearview image when the vehicle is placed in reverse - **crash risk**.


 **United States 30 October 2023:** Forest River Bus LLC is recalling 31 units of 2021-2022 Starcraft Allstar XL, 2022-2023 Allstar XLT and 2022 Glaval Concorde II transit buses because the exterior-mounted air conditioning compressor may contact the optional stabilizer/sway bar, possibly causing mount failure and resulting in a loss of power or steering control - **crash risk**.


 **Canada 27 October 2023:** Altec Industries is recalling 2 units of 2023 Altec DC and DM Series digger derricks because the gearbox assembly may not have been manufactured properly - **injury risk**.

 **Canada 27 October 2023:** Nissan is recalling 187 units of 2023 Nissan Z vehicles because the fasteners for the left-hand front bumper may not be tightened properly - **injury risk**.


 **Canada 27 October 2023:** Ferrari is recalling 62 units of 2022-2024 Ferrari SF90 vehicles because the turbocharger oil pipes could leak - **fire risk**.


 **United States 27 October 2023:** Ford Motor Company is recalling 187,922 units of 2020-2023 Mustang vehicles because the brake fluid level sensor may not activate the visual warning indicator when the brake fluid is low - **crash risk**.


 **United States 27 October 2023:** Winnebago Industries Inc. is recalling 280 units of 2024 Solis motorhomes because the fasteners that secure the sliding seat in the extended position are missing - **injury risk**.


 **Canada 26 October 2023:** Lucid is recalling 13 units of 2022-2023 Lucid Air vehicles because a software problem could cause the heater temperature for the rear seats not to be monitored


which could result in the rear heated seats remaining on, even if they get too hot - **injury risk**.


 **Canada 26 October 2023:** Fiat Chrysler Automobiles is recalling 6,642 units of 2022-2024 Jeep Grand Wagoneer and Wagoneer vehicles because the third-row seat belt buckles may not be accessible or may have been damaged during production - **injury risk**.


 **Canada 26 October 2023:** New Flyer is recalling 266 units of 2020-2023 New Flyer XD35 and 2019-2024 (not incl. 2023) New Flyer XD40 transit buses because the transmission yoke bolt could loosen and cause the driveshaft to separate from the transmission - **crash/injury risk**.

 **Canada 26 October 2023:** Toyota is recalling 2020-2023 Toyota Highlander and 2020-2023 Toyota Highlander Hybrid vehicles because the front lower bumper cover may not be attached properly - **crash risk**.


 **Canada 26 October 2023:** PACCAR is recalling 1,532 units of 2018-2024 Kenworth C500, T800 and W900 trucks because a spacer installed between the seat frame and the seat belt buckle may cause the seat belt to slip and not to work properly in a crash - **injury risk**.


 **Canada 26 October 2023:** Textron is recalling 114 units of 2022-2024 Cushman Hauler electric light utility vehicles because a problem with the lithium battery system could cause a fire even while parked with the ignition off - **fire risk**.


 **United States 26 October 2023:** Lamborghini is recalling 48 units of 2022 Urus vehicles because the infotainment system may become damaged which can result in an inoperative rearview camera display - **crash risk**.


 **United States 26 October 2023:** Kia America Inc. is recalling 6,262 units of 2015-2019 Soul EV vehicles because the parking mechanism may be damaged which can result in unintended vehicle


movement when the gear shift lever is in the Park 'P' position and the parking brake is not applied while the vehicle is powered on - **crash risk**.


 **United States 26 October 2023:** Chrysler is recalling 97,066 units of 2022-2024 Jeep Wagoneer and Grand Wagoneer vehicles because the third-row seat belts may not allow occupants to properly access or fasten the seat belt to the buckle - **injury risk**.

 **United States 26 October 2023:** Mazda North American Operations is recalling 11,903 units of 2024 CX-90 and MAZDA3 vehicles because due to a software error, the rearview, front, and/or side camera images may not appear on the display - **crash/injury risk**.


 **United States 26 October 2023:** Mazda North American Operations is recalling 2024 CX-90 plug-in hybrid electric (PHEV) vehicles because due to a software error, the engine and electric motor may shut down unexpectedly which can result in a loss of drive power - **crash risk**.


 **United States 26 October 2023:** PACCAR Incorporated is recalling 3,841 units of 2020 Kenworth T660, 2018-2024 Kenworth T800 and W900 vehicles because an additional spacer may have been added to the joint that connects the seat to the seat belt tether and buckle, causing an unsecured connection - **injury risk**.


 **United States 26 October 2023:** Weldon Division of Akron Brass is recalling 6,220 units of 8x16 Input-Output Node Vehicle Multiplex Systems because in the event of a short circuit or wiring failure, the firmware may fail to shut off the output pin resulting in overloaded electrical circuits - **fire risk**.


 **United States 26 October 2023:** Nissan North America Inc. is recalling 988 units of 2023-2024 Nissan Z vehicles because the fasteners in the left-side front bumper reinforcement clip may


loosen which can prevent the pop-up engine hood from activating - **injury risk**.


 **United States 26 October 2023:** Subaru of America Inc. is recalling 49 units of 2024 Forester vehicles because the engine water pipe may have loose attachment bolts, allowing the pipe to lose its seal and leak coolant - **fire risk**.

 **United States 26 October 2023:** Toyota Motor Engineering & Manufacturing is recalling 750,795 units of 2020-2023 Highlander & Highlander Hybrid vehicles because during normal vehicle operation, minor impact to the front lower bumper cover may result in the cover coming loose or detaching - **crash risk**.

 **United States 26 October 2023:** New Flyer of America Inc. is recalling 2,351 units of 2019-2024 XD35, XD40, XN35 and XN40 transit buses because the transmission yoke may separate, resulting in driveshaft separation and a sudden loss of drive power - **crash risk**.

 **Canada 25 October 2023:** Porsche is recalling 572 units of 2022-2024 Porsche 911 Carrera, 911 GT3 and 911 Turbo vehicles, equipped with optional full bucket seats, because the seat-mounted airbags could deploy in a crash that doesn't require them to - **injury risk**.


 **United States 25 October 2023:** Porsche Cars North America Inc. is recalling 2,923 units of 2021-2023 911 Turbo S, 2022 911 Turbo, 2022-2023 911 GT3 Touring, 911 GT3, 911 Carrera 4 GTS, 2022-2024 911 Carrera GTS, 2023 911 GT3 RS, 911 Dakar and 2024 911 Carrera T vehicles equipped with optional full bucket seats, because the seat-mounted air bags may deploy unnecessarily during a crash - **injury risk**.


 **United States 25 October 2023:** Nova Bus (US) Inc. is recalling 514 units of 2015-2019 LFS and LFS Artic transit buses because the attachment hardware may have been incorrectly installed beneath the rear wheel well passenger





Automotive Recall Summary


seats, allowing the seat to detach from the frame
- **injury risk**.


 **United States 24 October 2023:** Mack Trucks Inc. is recalling 47 units of 2024 LR vehicles because the fasteners that connect the power steering assist cylinder to steering arm may be loose or missing - **crash risk**.

 **United States 24 October 2023:** Trans-Air Manufacturing Corp is recalling 36 units of Dual Compressor Mounts because the compressors may contact the optional stabilizer/sway bar installed on certain Starcraft Ford F650 buses, possibly causing mount failure and resulting in a loss of power or steering control - **crash risk**.


 **United States 23 October 2023:** Midwest Automotive Designs LLC is recalling 64 units of 2017-2022 Luxe Cruiser, Ultimate Club J and Ultimate Presidential motorhomes because the alloy wheels installed on the vehicles are insufficient for the vehicle weight which can cause the wheels to crack and fail - **crash risk**.


 **Canada 20 October 2023:** Forest River is recalling 4 units of 2023 Coachmen Concord motorhomes because the suspension that was installed could cause an incorrect driveshaft angle which could cause the driveshaft to fail and cause the rear wheels to lock up - **crash risk**.


 **Canada 20 October 2023:** Forest River is recalling 6 units of 2023-2024 Coachmen Cross Trail motorhomes because the refrigerator may not have been secured properly - **injury risk**.


 **United States 20 October 2023:** BMW of North America LLC is recalling 155,627 units of 2010-2012 1 Series Coupe, 1 Series Convertible, 3 Series Sedan, 3 Series Convertible, 2010-2011 3 Series Sportswagon, 3 Series Coupe, 5 Series Sedan, X3 xDrive 28i, X3 xDrive 30i, X5 xDrive30i and Z4 sDrive30i vehicles because the aluminium bolts that secure the housing for the variable


camshaft timing adjustment (VANOS) unit can loosen over time and possibly break - **crash risk**.


 **United States 20 October 2023:** New Flyer of America Inc. is recalling 188 units of 2021-2023 XD35, 2022-2023 XD40, XD60, XN35, XN60, 2022 XDE35 and 2021-2022 XE40 transit buses because the Gross Axle Weight Rating (GAWR) and Gross Vehicle Weight Rating (GVWR) listed on the certification labels are incorrect which can allow the vehicle to be overloaded - **crash risk**.


 **United States 20 October 2023:** Lion Electric Company is recalling 7 units of 2024-2025 LionC School Buses because the anti-lock brake system (ABS) pneumatic valve connections and rear wheel speed sensors may be installed incorrectly - **crash risk**.


 **United States 20 October 2023:** Forest River Inc. is recalling 33 units of 2023-2024 Coachmen Cross Trail Class C motorhomes because the 12-volt refrigerator may dislodge and fall from its cabinet - **injury risk**.


 **Canada 19 October 2023:** Bombardier Recreational Products is recalling 2,285 units of 2022-2023 Bombardier Recreational Products Traxter, 2022-2023 Can-Am Commander, Defender and Maverick Trail vehicles because the owner's manual provides incorrect maintenance interval information for the driven clutch pulley - **injury risk**.


 **Canada 19 October 2023:** General Motors is recalling one 2023 Cadillac Lyriq vehicle because the connections within the high-voltage battery pack may be out of position or may not have been properly welded - **crash risk**.


 **Canada 19 October 2023:** Honda is recalling 53 units of 2022-2024 Honda Civic vehicles because the incorrect steering gear box assembly may have been installed during a repair - **crash risk**.


 **United States 19 October 2023:** Honda is recalling 176,410 units of 2022-2024 Civic 4-door and Civic 5-door vehicles that received a replacement power steering rack as part of a service repair, because the steering rack may have been incorrectly assembled which can allow the tire to chafe against the lower suspension or tie rod end, possibly resulting in tire damage - **crash/injury risk**.

 **United States 19 October 2023:** Jaguar Land Rover North America LLC is recalling 501 units of 2019-2023 I-PACE vehicles previously repaired under another recall, because the previous repair may not have been completed correctly and still allow the high-voltage battery to overheat - **fire risk**.


 **United States 19 October 2023:** Alliance RV LLC is recalling 3,390 units of 2021-2023 Paradigm and Valor fifth wheel trailers because a wire connector from the solar panel ports to the solar charge lines may loosen - **fire risk**.


 **Canada 18 October 2023:** BMW is recalling 547 units of BMW 2024 5 series, 2023-2024 7 series, 2024 i5 and 2023-2024 i7 vehicles because the steering wheel hands-on detection system may not detect when the driver removes their hands from the steering wheel - **crash risk**.


 **United States 18 October 2023:** Harbor Freight Tools is recalling 20,200 units of Kenway 17" LED Rear Tri-Marker Bar Running Lights because during packaging, these lights may have been damaged causing the lights to not illuminate - **crash risk**.


 **United States 18 October 2023:** BMW of North America LLC is recalling 9,211 units of 2023-2024 740i, 740i xDrive, 760i xDrive, i7 eDrive50, i7 xDrive60, i7 M70, 2024 750e xDrive, 530i, 530i xDrive, i5 eDrive40 and i5 M60 vehicles because the ground connection to the steering wheel may not have been attached correctly


resulting in an inoperative hands-on detection system - **crash risk**.


 **Canada 17 October 2023:** Fiat Chrysler Automobiles is recalling 834 units of 2023-2024 Alfa Romeo and 2023-2024 Dodge Hornet plug-in hybrid (PHEV) vehicles because the pedestrian alert siren may be missing or not connected properly - **injury risk**.


 **Canada 17 October 2023:** Ford is recalling 453 units of 2023 Ford F-150 Lightning (electric) trucks because the electronic cabin coolant heater may not have been manufactured correctly - **crash risk**.


 **United States 17 October 2023:** Chrysler is recalling 4,660 units of 2023-2024 Dodge Hornet and Alfa Romeo Tonale Plug-In Hybrid vehicles because the pedestrian alert siren may be missing or disconnected and fail to alert pedestrians when the vehicle is in reverse - **injury risk**.


 **United States 17 October 2023:** Ferrari North America Inc. is recalling 614 units of 2022-2024 SF90 Stradale and SF90 Spider hybrid electric vehicles because the turbocharger oil delivery pipe may have been manufactured incorrectly which can lead to an oil leak - **fire risk**.


 **United States 17 October 2023:** Autocar LLC is recalling 104 units of 2016-2023 ACX (Xpeditor) and 2021-2023 DC (Legend) vehicles because the park brake warning light may incorrectly illuminate during an air loss event - **crash risk**.


 **United States 17 October 2023:** Proterra Operating Company Inc. is recalling 238 units of 2019-2022 40' and 35' Catalyst 800V transit buses equipped with ProDrive 1.0 and 40' and 35' ZX5 800V transit buses equipped with ProDrive 1.0, because a transistor inside the inverter may overheat and fail which can result in a loss of power steering and drive power - **crash risk**.


 **United States 17 October 2023:** Cummins Inc. is recalling 104 units of L9N Natural Gas Engines because the rear lifting bracket that attaches to the engine cylinder head may be insufficiently secured which can allow it to detach - **injury risk**.


 **Canada 16 October 2023:** Ford is recalling 221 units of 2023 Ford Explorer vehicles because a problem with the rearview camera wiring harness could cause the rearview camera image not to display - **crash risk**.

 **United States 16 October 2023:** Storyteller Overland is recalling 265 units of 2022-2023 Ford Transit Storyteller Mode LT motorhomes because the tire and loading information label may indicate an incorrect tire size and pressure - **crash risk**.


 **United States 13 October 2023:** Kia America Inc. is recalling 22,768 units of 2009-2014 Borrego vehicles because the headliner plates may not be secured properly which can result in the plates detaching in the event of a side curtain air bag deployment - **injury risk**.


 **United States 13 October 2023:** Ford Motor Company is recalling 931 units of 2023 F-150 Lightning pickup trucks because the electronic cabin coolant heater module may be missing a solder joint which can cause intermittent or no cabin heat and result in an inoperative windshield defrosting and defogging system - **crash risk**.


 **United States 13 October 2023:** Ford Motor Company is recalling 2,866 units of 2023 Explorer vehicles equipped with a standard rearview camera, because due to a manufacturing error in the wire harness, the rearview camera may display a blue image on the SYNC screen when the vehicle is placed in reverse - **crash risk**.


 **United States 13 October 2023:** Ford Motor Company is recalling 34,762 units of 2021-2022 Mustang Mach-E vehicles equipped with an


extended range battery, because the high voltage battery main contactors may overheat - **crash risk**.


 **United States 13 October 2023:** Volvo Trucks North America is recalling 1,933 units of 2024 VNL, VHD and VNR trucks because the fastener that connects two steering components, the pitman arm and draglink, may be loose which can cause the connection to fail and result in a loss of steering control - **crash risk**.


 **United States 13 October 2023:** Volvo Trucks North America is recalling 29 units of 2024 Volvo VNL and VNR trucks because a software programming error may cause the electronic stability control (ESC) to be inoperative - **crash risk**.

 **United States 13 October 2023:** Arcimoto Inc. is recalling 94 units of 2023 FUV and MUV hybrid electric motorcycles because there may be insufficient thread engagement between the inner and outer tie rods, possibly resulting in the separation of the tie rod assembly - **crash risk**.


 **United States 13 October 2023:** Mack Trucks Inc. is recalling 13 units of 2024 Anthem and Pinnacle vehicles because a software programming error may cause the electronic stability control (ESC) to be inoperative - **crash risk**.


 **Canada 12 October 2023:** BrightDrop is recalling 17 units of 2023-2024 BrightDrop ZEVO 600 vehicles equipped with an optional passenger seat, because the wrong right-side B-pillar trim may have been installed - **injury risk**.


 **Canada 12 October 2023:** General Motors is recalling 5 units of 2024 Cadillac XT5 and 2023 GMC Acadia vehicles because the windshield may not be attached properly - **injury/crash risk**.


 **Canada 12 October 2023:** General Motors is recalling 6 units of 2023 Cadillac Lyriq vehicles because a software problem could cause the


pedestrian warning sounds not to work when the vehicle slows from 30 to 25 km/h - **injury risk**.


 **United States 12 October 2023:** General Motors LLC is recalling 42 units of 2023 GMC Acadia and 2024 Cadillac XT5 and XT6 vehicles because the windshield may have been assembled without the proper urethane sealant required to bond the windshield to the vehicle body - **injury risk**.


 **United States 12 October 2023:** General Motors LLC is recalling 62 units of 2023 Cadillac LYRIQ vehicles because the body control module (BCM) may have been updated with incorrectly calibrated software and fail to make the pedestrian warning sounds - **crash risk**.


 **United States 12 October 2023:** General Motors LLC is recalling 234 units of 2023-2024 Brightdrop Zevo 600 vehicles equipped with an optional passenger jump seat, because an incorrect passenger-side upper B-pillar trim panel may have been installed which can interfere with proper deployment of the right-side roof-rail air bag - **injury risk**.


 **United States 12 October 2023:** Southeast Toyota Distributors LLC is recalling 13 units of 2023 Toyota 4Runner vehicles because the load carrying capacity modification label states the incorrect load carrying capacity which can result in an overloaded vehicle - **crash risk**.


 **United States 12 October 2023:** T.A. Pelsue is recalling 164 units of 2022 Tradesman Fiberlite POD and Tradesman Fiberlite XL trailers because the welded-on trailer tongue may detach from the trailer frame - **crash/injury risk**.


 **United States 12 October 2023:** Hyundai Translead is recalling 562 units of 2022-2024 CGN3-20/40 and CGNS-20/40 12-Pin extended chassis because the cross braces located above the chassis air tanks may have been improperly welded - **crash risk**.


 **Canada 11 October 2023:** Continental Tire is recalling 1,282 units of 2023 Continental CrossContact LX25 225/65R17 and LX25 235/55R18 tires because the rubber compound may be contaminated with small metal fragments - **crash risk**.


 **Canada 11 October 2023:** Tesla is recalling 3,233 units of 2021-2023 Tesla Model X vehicles because the low brake fluid warning lamp may not turn on if the brake fluid level gets too low - **crash risk**.


 **United States 11 October 2023:** Tesla Inc. is recalling 54,676 units of 2021-2023 Model X vehicles because the vehicle controller may fail to detect low brake fluid and will not display a warning light - **crash risk**.


 **United States 11 October 2023:** Allison Transmission Inc. is recalling 8,498 units of B3400xFE_R and B400R transmission yokes because they may separate, resulting in driveshaft separation and a sudden loss of drive power - **injury risk**.


 **Canada 10 October 2023:** Harley-Davidson is recalling 193 units of 2023 Harley-Davidson CVO Road Glide and CVO Street Glide motorcycles because the rear brake line may not be secured correctly - **crash risk**.


 **United States 10 October 2023:** Platinum Driveline Inc. is recalling 167 units of Mustang clutch covers because the clutch cover may have been manufactured with material that may break - **injury risk**.


 **United States 10 October 2023:** AMETEK ICVS is recalling 18,239 units because the Ignition Control Module (ICM) software error may cause loss of drive power or loss of key safety functions, such as loss of head lights or windshield wipers - **crash risk**.


 **Canada 06 October 2023:** Trail King is recalling 386 units of 1992-2023 Trail King TKAB, TKFA and TKPA flip axle and pin-on axle trailers equipped with a booster, because the booster axle could lose pressure - **crash risk**.


 **Canada 06 October 2023:** Mercedes-Benz is recalling 410 units of Mercedes-Benz SL Class vehicles because the starter wiring harness may have been routed incorrectly - **crash/fire risk**.


 **United States 06 October 2023:** Ford Motor Company is recalling 238,364 units of 2020-2022 Explorer vehicles because the rear axle horizontal mounting bolt may fracture and cause the driveshaft to disconnect - **crash risk**.


 **United States 06 October 2023:** Mercedes-Benz USA LLC is recalling 5,326 units of 2022-2023 AMG SL55 and AMG SL63 vehicles because the electrical wiring harness for the starter and alternator may not be secured properly which can result in a short circuit and a loss of drive power or cause the harness to overheat - **fire risk**.


 **United States 06 October 2023:** Mercedes-Benz USA LLC is recalling one 2022 EQB 350 vehicle because the incorrect child seat anchor covers may have been installed on the second-row seat - **injury risk**.


 **United States 06 October 2023:** Transfer Flow Inc-Chico CA is recalling 4,240 units of TRAX 4 Control Modules because the auxiliary fuel tank control module may unexpectedly pump fuel into the primary fuel tank which can cause the tank to overflow and leak fuel - **fire risk**.


 **Canada 05 October 2023:** Polaris is recalling 175 units of 2023-2024 Polaris Ranger XP Kinetic UTVs because the throttle may not work when the brake and throttle pedals are applied at the same time - **crash risk**.


 **United States 05 October 2023:** Jayco Inc. is recalling 46 units of 2024 Jayco Precept and Entegra Coach Vision XL motorhomes because the window shade may obstruct the emergency exit window opening - **injury risk**.


 **United States 04 October 2023:** Lightning eMotors Inc. is recalling 239 units of 2021-2022 FT3-40, 2021-2023 FT3-80, and 2022-2023 FT3-120 vehicles because the instrument cluster may not activate the "Brake," "Park," and "ABS" indicator warning lights during the light function check when the ignition is turned to the "on" (run) position - **crash risk**.

 **United States 04 October 2023:** Dorman Products Inc. is recalling 27,528 units of Suspension Ball Joints because the ball stud may separate from the lower control arm which can lead to loss of steering control - **crash risk**.

 **United States 04 October 2023:** Volkswagen Group of America Inc. is recalling 2 units of 2019 Atlas vehicles because the driver's side impact air bag may be missing a weld at the side air bag housing - **injury risk**.

 **United States 04 October 2023:** Harley-Davidson Motor Company is recalling 2,212 units of 2023 FLHXSE and FLTRXSE motorcycles because the rear brake line may not be secured properly, allowing it to chafe against the exhaust pipe, which can result in a brake fluid leak - **crash risk**.


 **Canada 03 October 2023:** Daimler Truck North America is recalling 16 units of 2020-2024 Thomas Built SAF-T-LINER C2 Non-School Bus school buses because the fasteners for the rear emergency exit door latch could loosen and detach - **injury risk**.


 **Canada 03 October 2023:** Daimler Truck North America is recalling 1,892 units of 2019-2024 Thomas Built SAF-T-LINER C2 School Bus school buses because the fasteners for the rear





Automotive Recall Summary


emergency exit door latch could loosen and detach - **injury risk**.


 **United States 03 October 2023:** Zero Motorcycles Inc. is recalling 306 units of accessory chain kits because the included installation instructions are incorrect and if followed, may lead to eventual dislocation of the motor shaft magnet while riding - **crash risk**.


 **United States 03 October 2023:** Volvo Bus Corporation is recalling 14 units of 2023 Volvo 9700 vehicles because the fasteners that secure the power cable connections may not have been tightened securely - **fire risk**.


 **United States 03 October 2023:** Volvo Bus Corporation is recalling 14 units of 2023 Volvo 9700 buses because the emergency window exits may be missing identification and operating instruction labels - **injury risk**.


 **United States 03 October 2023:** Daimler Trucks North America LLC is recalling 173 units of 2019-2024 Thomas Built SAF-T-LINER C2 transit buses because the fasteners for the emergency exit door may loosen and detach which can allow the emergency exit door to open unexpectedly - **injury risk**.


 **United States 03 October 2023:** Daimler Trucks North America LLC is recalling 20,668 units of 2019-2024 Thomas Built SAF-T-LINER C2 and 2020-2024 Thomas Built SAF-T-Liner Jouley school buses because the fasteners for the emergency exit door may loosen and detach which can allow the emergency exit door to open unexpectedly - **injury risk**.

 **United States 02 October 2023:** Mercedes-Benz USA LLC is recalling 32 units of 2022 A220, GLA250 and AMG GLA35 vehicles because the headlights may be incorrectly adjusted - **crash risk**.

 **United States 02 October 2023:** Harley-Davidson Motor Company is recalling 1,139 units of 2023 X350 RA motorcycles because the fuel sensor may leak fuel - **fire risk**.

 **United States 02 October 2023:** Continental Tire the Americas LLC is recalling 3,472 units of CrossContact LX25 tires because they may contain rubber compound contaminated with small metal fragments - **crash risk**.

 **United States 02 October 2023:** HL Mando Corporation is recalling 3,372,743 units because the Anti-Lock Brake System (ABS) module may leak brake fluid internally and cause an electrical short which can result in an engine compartment fire while parked or driving - **injury risk**.

 **United States 02 October 2023:** REV Recreation Group is recalling 14 units of 2023-2024 Fleetwood Fortis and 2024 Holiday Rambler Invicta motorhomes because the exterior griddle may be stowed while still connected to the LP gas line - **fire risk**.

Get in touch with one of our Product Recall Specialists for analysis on any of the above recall events.



US: +1 305 384 4825

APAC: +61 2807 30186

UK & EU: +44 20 3284 8844

This report (including any enclosures and attachments) has been prepared for the exclusive use and benefit of the addressee(s) and solely for the purpose for which it is provided. Unless we provide express prior written consent, no part of this report should be reproduced, distributed or communicated to any third party. Security Exchange Limited does not accept any liability if this report is used for an alternative purpose from which it is intended. The conclusions and recommendations contained herein are offered for the consideration of the addressee and are based on the information made available at the time of reporting. The addressee is under no obligation to adopt any of the recommended measures and Security Exchange limited cannot be held liable for any resulting errors or omissions.



Automotive Recall Summary