

## August 2023



### North America



**Canada 31 August 2023:** General Motors is recalling 1,241 units of 2022-2023 Chevrolet Bolt EUV vehicles because the included portable charging cord could have incorrect software - **injury risk**.



**United States 31 August 2023:** General Motors LLC is recalling 9,423 units of Webasto Portable Charging Cords (Gen 3) because these charging cords contain incorrect software and may fail to discontinue charging if the ground connection is lost - **injury risk**.



**United States 31 August 2023:** Kia America Inc. is recalling 144,979 units of 2022-2023 Sorento, Sorento Hybrid and Sorento Plug-in Hybrid (PHEV) vehicles because the mounting clips for the rearview camera may break which can

cause the rearview camera image not to appear properly on the display - **crash risk**.



**United States 31 August 2023:** Subaru of America Inc. is recalling 8,915 units of 2022 BRZ and Toyota GR86 vehicles because the rear turn signals may intermittently become inoperative - **crash risk**.





**United States 31 August 2023:** Subaru of America Inc. is recalling 8,915 units of 2022 BRZ and Toyota GR86 vehicles because the rear turn signals may intermittently become inoperative - **crash risk**.





**United States 31 August 2023:** Triple E Recreational Vehicles is recalling 391 units of 2021-2022 Unity U24IB and 2021-2023 U24TB motorhomes because the battery disconnect switch may contact the refrigerator frame causing it to short circuit and blow the fuse - **fire risk**.


# Automotive Recall Summary


 **United States 31 August 2023:** Nova Bus Inc. is recalling 1,189 units of 2017-2023 LFS and 2017-2022 LFS Artic transit buses because the 24-volt power cable and grounded mounting fastener that secures the fuse holder may short circuit - **fire risk**.


 **Canada 30 August 2023:** Kubota is recalling 119 units of 2022-2023 Kubota RTV-XG850 side-by-side UTVs because the steering shaft may not have been assembled correctly - **crash risk**.


 **United States 30 August 2023:** Volkswagen Group of America Inc. is recalling 47,651 units of 2019-2020 Jetta vehicles equipped with a conventional ignition switch because the ignition switch may fail, especially in high temperature environments - **crash risk**.


 **United States 30 August 2023:** Mack Trucks Inc. is recalling 395 units of 2024 MD6 and MD7 vehicles because the steering gear fasteners may not be properly tightened - **crash risk**.


 **United States 30 August 2023:** Corp. Micro Bird Inc. is recalling 6 units of 2018-2019 and 2021 G5 transit buses because the seats located over the fuel filler and equipped with seat belts may detach - **injury risk**.


 **United States 30 August 2023:** Interstate Group LLC is recalling 263 units of 2022-2023 ITLT716SA2 trailers because the steel tie-down flat straps could interfere with the operation of the trailer deck tilt latch when the trailer load is unevenly distributed - **injury risk**.


 **Canada 29 August 2023:** Textron is recalling 695 units of 2022-2023 Arctic Cat Prowler Pro, Arctic Cat Prowler Pro Crew, Tracker Off Road 800 SX and Tracker Off Road 800 SX Crew side-by-side UTVs because the dash can display that the transmission is in park "P" when the shifter isn't fully in the park position - **crash/injury risk**.


 **Canada 29 August 2023:** Ford is recalling 2,997 units of 2023 Ford F-250 Super Duty and F-350 Super Duty trucks because the left-rear axle shaft may not have been manufactured properly which could cause the axle shaft to break and cause a loss of power to the wheels - **crash/injury risk**.


 **Canada 28 August 2023:** Ford is recalling 14,949 units of 2021 Ford Bronco, 2022-2023 Ford Transit and 2018-2021 Lincoln Navigator vehicles, equipped with a 360-degree camera, because a software problem could cause the rearview camera image not to appear on the SYNC display screen - **crash risk**.

 **Canada 25 August 2023:** Mack is recalling 5,280 units of 2015-2023 Mack Granite and Mack GU trucks because the front turn signals may not be visible from certain angles - **crash risk**.

 **United States 25 August 2023:** Ford Motor Company is recalling 8,523 units of 2023 Edge vehicles because the front right headlight may be too bright or aimed incorrectly - **crash risk**.


 **United States 25 August 2023:** Ford Motor Company is recalling 169,277 units of 2020-2023 Lincoln Aviator, 2018-2021 Lincoln Navigator, 2022-2023 Ford Transit and 2021 Ford Bronco vehicles because the rearview camera, or 360-degree view camera if equipped, may not display a rearview image when the vehicle is placed in reverse - **crash risk**.


 **United States 25 August 2023:** Ford Motor Company is recalling 10 units of 2023 Explorer vehicles equipped with 2.3L GTDI engines because the turbocharger oil supply line may be damaged which can result in an oil leak inside the engine compartment - **fire/crash risk**.


 **United States 25 August 2023:** Ford Motor Company is recalling 41,555 units of 2023 Super Duty F250 and F350 vehicles equipped with single rear wheels and a 10.5-inch rear axle shaft because the left rear axle shaft may have been


# Automotive Recall Summary


improperly heat-treated during manufacturing and may break - **crash risk**.


 **United States 25 August 2023:** Hyundai Motor America is recalling 63 units of 2024 Palisade vehicles equipped with dark premium suede seats because the Occupant Detection System (ODS) may fail to detect an occupant and deactivate the passenger-side front air bags - **injury risk**.

 **United States 25 August 2023:** Volkswagen Group of America Inc. is recalling 7,499 units of 2021 Audi S7, S6 Sedan, RS7, RS6 Avant, A6 Allroad, 2019-2021 A7 and A6 Sedan vehicles because an incorrectly labelled brake fluid cap may have been installed which can result in the use of the wrong type of brake fluid - **crash risk**.


 **United States 25 August 2023:** Fruehauf Inc. is recalling 786 units of 2025 Composite trailers equipped with Tire Pilot Plus tire pressure regulation systems (TPRS) because all 8 tires may experience a loss of tire pressure while driving faster than 45 mph - **crash risk**.


 **United States 25 August 2023:** Mack Trucks Inc. is recalling 27,418 units of 2015-2023 GU and GR vehicles because the turn signals may be positioned incorrectly, reducing their visibility - **crash risk**.


 **Canada 24 August 2023:** Harley-Davidson is recalling 103 units of Harley-Davidson 2019-2020 FXDR 114, 2018-2023 Heritage Classic, 2018-2023 Softail Breakout, 2018-2020 Softail Deluxe, 2018-2022 Softail Low Rider, 2018-2021 Softail Slim, 2018-2021 Softail Sport Glide, 2020-2023 Softail Standard and 2018-2023 Softail Street Bob motorcycles because the screw that attaches the rear shock absorber adjuster could break which could cause damage to the rear tire - **crash risk**.


 **Canada 24 August 2023:** Harley-Davidson is recalling 4,130 units of Harley-Davidson 2018-2023 Heritage Classic, 2018-2019 Softail Deluxe and 2020-2023 Softail Low Rider motorcycles


because a screw that attaches the rear shock absorber adjuster could break which could cause damage to the rear tire - **crash risk**.


 **Canada 24 August 2023:** General Motors is recalling 163,611 units of 2021-2023 Cadillac Escalade, 2021-2023 Cadillac Escalade ESV, 2022-2024 Chevrolet Silverado, 2024 Chevrolet Silverado HD, 2021-2023 Chevrolet Suburban, 2021-2023 Chevrolet Tahoe, 2022-2024 GMC Sierra, 2024 GMC Sierra HD, 2021-2023 GMC Yukon and 2021-2023 GMC Yukon XL vehicles because the automatic headlamps may not turn on soon enough as it becomes dark outside - **crash risk**.

 **United States 24 August 2023:** Kia America Inc. is recalling 319,436 units of 2016-2017 Rio, 2016-2018 Optima, 2017-2018 Optima Hybrid and Optima Plug-in Hybrid vehicles because the trunk latch base may crack, preventing the opening of the trunk from the inside - **injury risk**.

 **United States 24 August 2023:** Harley-Davidson Motor Company is recalling 1,282 units of Profile Low Rear Suspension and Tall Rear Shocks that were sold as H-D Parts & Accessories, because a fastener securing the rear shock absorber may break and allow the rear shock absorber adjuster to damage the rear tire, causing a loss of tire pressure - **crash risk**.

 **United States 24 August 2023:** Streamline Industries Incorporated is recalling 30,000 units of LA Chopper Brake Hose Kits because the hydraulic brake hoses may fail - **crash risk**.

 **Canada 23 August 2023:** Bentley is recalling 309 units of 2017-2023 Bentley Bentayga vehicles because the fuel supply module connectors and wiring could overheat which could cause the fuel supply module to melt and create a fuel leak - **fire risk**.


 **Canada 23 August 2023:** Triple E Canada is recalling 134 units of 2021-2023 Leisure Travel Vans Unity motorhomes because the connections on the battery disconnect switch (located near the





# Automotive Recall Summary


entry door) could contact the refrigerator frame - **fire risk**.


 **United States 23 August 2023:** Volkswagen Group of America Inc. is recalling 2,018 units of 2024 Atlas PA2 and Atlas Cross Sport PA vehicles because the engine connecting rod bearings may become damaged which can result in engine failure - **fire risk**.


 **United States 23 August 2023:** Bentley Motors Inc. is recalling 3,527 units of 2017-2023 Bentayga vehicles because the fuel supply module wiring can overheat and melt the flange, resulting in a fuel leak - **fire risk**.


 **United States 23 August 2023:** Yokohama Tire Corporation is recalling 6,992 units of 504C tires because a defective belt cushion splice may allow air to leak into sidewall - **crash risk**.


 **United States 22 August 2023:** Harley-Davidson Motor Company is recalling 65,224 units of 2018-2019 FLDE, 2018-2021 FLHC, 2018-2023 FLHCS, 2018 and 2023 FLHCS ANV, 2020-2023 FXLRS, 2022-2023 FXLRST and 2022 FXRST Softail motorcycles because a fastener securing the rear shock absorber may break and allow the rear shock absorber adjuster to damage the rear tire, causing a loss of tire pressure - **crash risk**.


 **United States 21 August 2023:** Outfitter Manufacturing is recalling 78 units of 2021-2022 Caribou Lite 6.5, Caribou Lite 8, Caribou 6.5, Apex 8, 2021 Apex 8 LB and 2022 Caribou Lite 8.5 truck campers, equipped with certain SDS2 2-Burner Drop-in Cooktops, because the internal aluminium burner tubes that connect to the gas valves may fracture and cause a gas leak - **fire risk**.


 **United States 21 August 2023:** Aluminum Trailer Company (ATC) is recalling 58 units of 2022-2023 PL700 trailers because the wire connections in the transfer switch may be tightened improperly and loosen - **fire risk**.


 **Canada 18 August 2023:** Hyundai is recalling 6,014 units of 2021-2023 Hyundai Elantra vehicles because they could slowly accelerate after the brake pedal is released - **crash risk**.


 **United States 18 August 2023:** Hyundai Motor America is recalling 37,997 units of 2021-2023 Elantra HEV vehicles because a software error in the motor control unit may cause unintended vehicle acceleration after the brake pedal is released - **crash risk**.

 **Canada 17 August 2023:** Honda is recalling one 2023 CR-V Hybrid vehicle because the wiring inside the transmission could be damaged by a broken part and cause the vehicle not to work in hybrid mode - **crash risk**.

 **Canada 17 August 2023:** Navistar is recalling 51 units of 2023 International HV and International MV trucks because the driveshaft could break while driving and cause a sudden loss of power to the wheels - **crash risk**.

 **Canada 17 August 2023:** Kia is recalling 5,146 units of 2023 Kia Sorento vehicles because the airbag warning labels on the driver and passenger sun visors could peel off - **injury risk**.


 **Canada 17 August 2023:** Grand Design RV is recalling 80 units of 2022-2024 Grand Design Momentum Travel Trailer RV trailers because they were equipped with safety chains that are not strong enough which could result in the safety chains breaking if uncoupled from the tow vehicle - **crash risk**.


 **United States 17 August 2023:** Grand Design RV LLC is recalling 1,209 units of 2022-2024 Momentum 23G and 25G travel trailers because the installed safety chains are underrated for the Gross Vehicle Weight Rating (GVWR) - **crash risk**.


 **United States 17 August 2023:** Honda is recalling 19 units of 2023 CR-V Hybrid and Accord


# Automotive Recall Summary


Hybrid vehicles because the electronic transmission may have been improperly manufactured which can result in a loss of drive power - **crash risk**.


 **United States 17 August 2023:** Navistar Inc. is recalling 624 units of 2023 International MV and International HV vehicles because the driveshafts can break under certain loading conditions - **crash risk**.


 **Canada 16 August 2023:** Triumph is recalling 1,011 units of 2022-2024 Triumph Tiger and Triumph Trident motorcycles because a blockage within the manifold absolute pressure (MAP) sensor hose could cause the MAP sensor to provide incorrect information to the engine control unit - **crash risk**.


 **United States 16 August 2023:** BMW of North America LLC is recalling 144 units of 2019-2022 330i, 330i xDrive, M340i, 2022 430i Coupe, 2021-2022 430i, M440i Convertible and 2020-2022 228i xDrive Gran Coupe vehicles because the receiver audio module control unit software may fail to properly generate audible seat belt warnings to the driver to fasten their seat belt - **injury risk**.


 **United States 16 August 2023:** Triumph Motorcycles America Ltd is recalling 7,541 units of 2022-2024 Trident 660 and Tiger Sport 660 motorcycles because the manifold absolute pressure (MAP) hose may have an obstruction causing incorrect air pressure readings by the MAP sensor - **crash risk**.


 **United States 16 August 2023:** Entrants International LLC is recalling 75 units of 2023 Polar Tank SCX9 trailers because the trailers may have been produced without a rear impact guard certification plate - **injury/crash risk**.


 **Canada 15 August 2023:** Polaris is recalling 3,144 units of Polaris 2023 Indy, 2022-2023 Polaris RMK and 2023 Polaris Switchback snowmobiles because the fuel line between the fuel rails could develop a fuel leak - **fire risk**.


 **Canada 15 August 2023:** Indian Motorcycle is recalling one 2023 Indian Motorcycle Pursuit because the fuel line may not have been assembled correctly - **crash risk**.


 **Canada 15 August 2023:** Polaris is recalling 2 units of 2023 Polaris Ranger XP 1000 Crew side-by-side UTVs because the passenger seat belt bracket may not have been properly welded - **injury risk**.


 **United States 15 August 2023:** Nissan North America Inc. is recalling 236,238 units of 2020-2022 Sentra vehicles because the left and/or right tie rod may bend - **crash risk**.

 **United States 15 August 2023:** Kia America Inc. is recalling 50,517 units of 2023 Sorento vehicles because the air bag warning labels on the driver and front passenger sun visors may detach - **injury risk**.

 **United States 15 August 2023:** Indian Motorcycle Company is recalling 45 units of 2023 Challenger, Pursuit Dark Horse Icon w/Premium Package, Pursuit Dark Horse w/Premium Package and Pursuit Limited w/Premium Package motorcycles because the fuel line may have been improperly assembled which can result in an engine stall - **crash/injury risk**.

 **United States 15 August 2023:** Nikola Corporation is recalling 209 units of 2022-2023 Tre BEV vehicles because the coolant may leak inside the battery pack - **fire risk**.


 **Canada 14 August 2023:** Fiat Chrysler Automobiles is recalling 12,043 units of 2022-2023 Jeep Compass vehicles because a software problem in the body control module (BCM) could cause the backlight for the instrument cluster display not to work correctly - **crash risk**.


 **Canada 14 August 2023:** Fiat Chrysler Automobiles is recalling 18,641 units of 2021-2023 Jeep Grand Cherokee, 2022-2024 Jeep Grand Wagoneer and 2022-2024 Jeep Wagoneer


# Automotive Recall Summary


vehicles because a software problem could cause the rearview camera image to not appear on the display screen - **crash risk**.


 **Canada 14 August 2023:** Forest River is recalling 16 units of 2023-2024 Forest River FR3 and Georgetown motorhomes because the Smart Data Link Connector (SDLC) module may have been damaged by moisture during vehicle assembly - **crash risk**.


 **Canada 14 August 2023:** Forest River is recalling 2 units of 2023 Forest River Isata motorhomes because the intake air heater relay could short circuit - **fire risk**.

 **United States 14 August 2023:** Chrysler is recalling 181,999 units of 2022-2023 Jeep Compass vehicles because the brightness level of the instrument panel cluster (IPC) may not be adjustable due to incorrect software in the body control module (BCM) - **crash risk**.


 **United States 14 August 2023:** Chrysler is recalling 162,713 units of 2022-2023 Jeep Grand Cherokee, 2021-2023 Jeep Grand Cherokee L and 2022-2024 Jeep Wagoneer and Grand Wagoneer vehicles because the Central Vision Park Assist module (CVPAM) software may prevent the rearview image from displaying when the vehicle is placed in reverse - **crash/injury risk**.


 **United States 14 August 2023:** Chrysler is recalling 1,114 units of Mopar Central Vision Park Assist Modules (CVPAM) because the module software may prevent the rearview image from displaying when the vehicle is placed in reverse - **crash/injury risk**.


 **United States 14 August 2023:** Chrysler is recalling 352 units of Mopar Body Control Modules (BCM) because the brightness level of the instrument panel cluster (IPC) may not be adjustable due to incorrect software in the body control modules (BCM) - **crash risk**.


 **United States 14 August 2023:** Trail King Industries Inc. is recalling 5,641 units of 1992-


2023 TKFA, TKPA, AB and AB EXT trailers, equipped with pin-on axles or pivot extensions, because the shims that transfer weight between the trailer and the pin-on axle may detach if the air line or air suspension lose compression - **crash risk**.


 **United States 14 August 2023:** Forest River Inc. is recalling 16 units of 2024 Coachmen Beyond, Galleria and Nova motorhomes, equipped with certain SmartPlug 30-Amp Shore Power Inlets, because the manganese bronze D-rings may crack or fail when over-tightened - **fire risk**.

 **Canada 11 August 2023:** Ford is recalling 2,059 units of 2023 Ford F-250 Super Duty, F-350 Super Duty and F-450 Super Duty trucks because a software problem could cause the wrong rearview camera image to display while reversing - **crash risk**.


 **Canada 11 August 2023:** Mercedes-Benz is recalling 50 units of 2023 Mercedes-Benz AMG GT and E Class vehicles because the exit warning feature may not work properly - **crash risk**.


 **United States 11 August 2023:** Ford Motor Company is recalling 18,513 units of 2023 F-Super Duty F250, F350 and F450 vehicles equipped with the Pro Trailer Hitch Assist feature because the default rearview camera image may not be displayed when using the Pro Trailer Hitch Assist feature - **crash/injury risk**.


 **United States 11 August 2023:** Mercedes-Benz USA LLC is recalling 880 units of 2023 E450, E350, AMG E63 S, AMG E53, CLS450, AMG GT53 and AMG GT43 vehicles because due to a software error, the exit warning system audio and visual warnings may fail to alert occupants about approaching vehicles - **crash/injury risk**.


 **Canada 10 August 2023:** Maserati is recalling 10 units of 2023 Maserati MC20 vehicles because on a small number of MC20 Cielo models, the windshield frame mounting stud may be missing sealant - **injury risk**.


# Automotive Recall Summary


 **Canada 10 August 2023:** General Motors is recalling 75 units of 2022-2023 Chevrolet Bolt EV vehicles because the instrument panel may not have been manufactured correctly which could cause the passenger-front airbag to not open and inflate properly in a crash - **injury risk**.

 **Canada 10 August 2023:** Toyota is recalling 17,299 units of 2022-2023 Toyota Tundra trucks because a plastic fuel tube on the top of the fuel tank may not be secured correctly - **fire risk**.

 **Canada 10 August 2023:** Isuzu is recalling 656 units of 2023-2024 Isuzu NPR, 2023-2024 Isuzu NPR-HD, 2024 Isuzu NQR and 2024 Isuzu NRR trucks because the seal on the fuse holders for the ignition coil packs may be too small which could cause water to leak into the fuses and cause them to corrode or fail - **crash risk**.


 **United States 10 August 2023:** Chrysler is recalling 16 units of 2023 Jeep Wrangler vehicles because the spare tire may obstruct the view of the centre high-mount brake light - **crash risk**.


 **United States 10 August 2023:** Isuzu Motors Limited is recalling 19,479 units of 2023-2024 NPR Gas, NPR HD Gas, 2024 NQR Gas, NRR Gas, 2023-2024 Chevrolet LCF 3500HG, Chevrolet LCF 4500HG, 2024 Chevrolet LCF 5500HG and Chevrolet LCF 5500XG vehicles because the chassis harness may have an incorrectly sized wire seal for the 2 externally mounted engine ignition coil pack fuse holders which can allow water intrusion and cause the fuses to corrode - **crash risk**.


 **United States 10 August 2023:** General Motors LLC is recalling 317 units of 2022-2023 Chevrolet Bolt EV vehicles because the instrument panel may be missing the perforation on the underside of the panel cover that allows the passenger-side air bag to deploy properly - **injury risk**.


 **United States 10 August 2023:** Jaguar Land Rover North America LLC is recalling one 2023


Land Rover Range Rover PHEV vehicle because a bolt for the high voltage battery may not be secured properly which can result in the high voltage battery sparking and overheating - **fire risk**.


 **United States 10 August 2023:** Maserati North America Inc. is recalling 59 units of 2023 MC20 Cielo vehicles because the windshield frame stud sealant, which retains the stud connecting the windshield frame to the body, may not have been installed which can reduce body structure performance and roof strength - **injury risk**.

 **United States 10 August 2023:** Toyota Motor Engineering & Manufacturing is recalling 168,179 units of 2022-2023 Tundra and Tundra Hybrid vehicles because the plastic fuel tube routed near metallic brake lines may chafe against the brake lines and become damaged, possibly resulting in a fuel leak - **fire risk**.

 **United States 10 August 2023:** Piaggio Group Americas Inc. is recalling 260 units of 2023 Moto Guzzi V100 Mandello and Mandello Aviazione Navale motorcycles because the rear shock absorber may be missing one or both bushings which can cause it to break - **crash risk**.


 **United States 10 August 2023:** Autocar LLC is recalling 605 units of 2023 ACX (Xpeditor) and DC (Legend) vehicles because the powertrain driveline centre support bearing hardware may not have been properly secured - **crash risk**.


 **United States 10 August 2023:** Alliance RV LLC is recalling 60 units of 2023-2024 Paradigm 295MK, 310RL, 340RL, 370FB, 382RK, 385FL, 390MP and 395DS travel trailers because the breakaway switch and trailer brakes may not activate when needed due to an incorrectly wired breakaway switch - **crash risk**.


 **Canada 09 August 2023:** Hino is recalling 1,286 units of 2020-2024 Hino L6, L7 and L8 trucks because the fuel gauge float inside the fuel tank could detach - **crash risk**.





# Automotive Recall Summary


 **United States 08 August 2023:** Explorer Van Company is recalling 8 units of 2020-2022 upfitted GMC Savana and 2020 upfitted Ford Transit vans, equipped with certain Onan QG 2800i generator sets, because the fuel hose between the fuel filter and Injection Pump Module (IPM) may not be properly secured which can cause a gas leak - **fire risk**.


 **United States 08 August 2023:** Hino Motors Sales USA Inc. is recalling 8,025 units of 2020-2024 NE7A, NE7B, NE8A, NH9A, NJ7A, NJ7B, NJ8A, NJ8J, NV7A, NV7B and NV8A vehicles, equipped with 70- or 90-gallon fuel tanks, because the fuel sender float may deform and detach which can lead to an inaccurate fuel gauge reading - **crash risk**.


 **Canada 07 August 2023:** Canadian Motor Import Inc. is recalling 56 units of 2023 CFMOTO IBEX 800 touring motorcycles because the mounting bolt for the right footrest may not have been properly tightened - **crash risk**.


 **Canada 07 August 2023:** Forest River is recalling one 2023 Palomino Pause RV trailer because the awning may not have been installed properly - **injury/crash risk**.


 **United States 07 August 2023:** Forest River Inc. is recalling 40 units of 2024 Sandpiper and Sierra fifth wheels because the axle may be installed backwards which can reduce braking ability - **crash risk**.


 **United States 07 August 2023:** Forest River Inc. is recalling 32 units of 2023 Forest River Pause travel trailers because the awning may not be adequately secured which can cause the awning to detach - **injury/crash risk**.


 **Canada 04 August 2023:** Hyundai is recalling 23 units of 2023 Genesis GV60 vehicles because the automatic locking retractor (ALR) feature on the passenger-front seat belt may not work properly - **injury risk**.


 **Canada 04 August 2023:** PACCAR is recalling 5 units of 2023-2024 Kenworth T280, 2024 Kenworth T380, 2023-2024 Kenworth T480, 2023-2024 Peterbilt 536, 2023-2024 Peterbilt 537 and 2023-2024 Peterbilt 548 trucks because the bolts that attach the driveshaft may loosen - **crash risk**.


 **United States 04 August 2023:** Mazda North American Operations is recalling 17,600 units of 2024 CX-90 vehicles because software in the Approaching Vehicle Audible System (AVAS) Information Sound Box (ISB) amplifier may be missing which can cause inaccurate, external pedestrian warning sounds - **injury/crash risk**.

 **United States 04 August 2023:** Hyundai Motor America is recalling 30 units of 2024 Tucson vehicles because the tire and loading information label may incorrectly indicate information about a spare tire - **injury/crash risk**.

 **United States 04 August 2023:** Hyundai Motor America is recalling 168 units of 2023 Genesis GV60 vehicles because the automatic locking retractor for the front passenger-side seat belt may prohibit the seat belt from fastening and/or extending properly - **injury risk**.

 **United States 04 August 2023:** Mercedes-Benz USA LLC is recalling 73 units of 2022-2023 Maybach S580 and Maybach S680 vehicles because the 12-Volt ground connection in the trunk may not be secured properly which can impair the electronic stability program (ESP) or result in the ground connection overheating - **crash/fire risk**.


 **United States 04 August 2023:** Mercedes-Benz USA LLC is recalling 10 units of 2023 AMG EQE, EQE 500 and EQE 350 vehicles because the absorbers in the roof frame may not be secured properly and can detach during window air bag deployment - **injury risk**.


 **United States 04 August 2023:** Subaru of America Inc. is recalling 35,357 units of 2024





# Automotive Recall Summary


Crosstrek and Impreza vehicles because due to insufficient clearance, the instrument panel harness may contact the steering beam bracket, damaging the wire insulation and causing a short circuit - **crash risk**.


 **United States 04 August 2023:** Nelson Trailers is recalling one 2018 CBC-40ST trailer, equipped with a Dexter Smart-Steer Axle with a bolt-on steering arm, because the steering arm may break during certain conditions, such as low speed and high side-loading - **crash risk**.


 **Canada 03 August 2023:** Lakota is recalling 3 units of Lakota Bighorn trailers because on a small number of 5 & 6 horse triple-axle trailers, the axle carriers were made with metal that's too thin - **crash risk**.

 **Canada 03 August 2023:** Starcraft RV is recalling one 2023 Starcraft Super Lite Maxx RV trailer because an emergency exit window may not have been installed - **injury risk**.


 **Canada 03 August 2023:** Highland Ridge is recalling 2 units of 2023 Highland Ridge RV Range Lite Air RV trailers because an emergency exit window may not have been installed - **injury risk**.


 **Canada 03 August 2023:** Fiat Chrysler Automobiles is recalling 2,990 units of 2022-2023 Jeep Grand Wagoneer and 2022-2023 Jeep Wagoneer vehicles because the upper B-pillar trim may not be installed correctly - **injury risk**.


 **United States 03 August 2023:** Chrysler is recalling 44,708 units of 2022-2023 Jeep Wagoneer and Grand Wagoneer vehicles because the upper B-pillar interior trim may not be fully seated and could interfere with the side curtain air bag (SABIC) deployment - **injury risk**.


 **United States 03 August 2023:** Ford Motor Company is recalling 2 units of 2023 Bronco vehicles because the transmission park system may have been damaged during assembly which


can prevent the parking pawl from fully engaging and result in a vehicle rollaway - **crash risk**.


 **United States 03 August 2023:** General Motors LLC is recalling 3,893 units of 2024 Chevrolet Silverado 2500, 3500 and GMC Sierra 2500, 3500 vehicles because the steering gear shaft may fracture and disconnect from the steering arm - **crash risk**.

 **United States 03 August 2023:** Lakota Corporation is recalling 65 units of 2020-2024 Bighorn and Charger Triple Axle 5&6 horse trailers because the main rails of the axle carrier may have been manufactured with an insufficient gauge steel which can cause the carrier to break - **crash risk**.


 **United States 03 August 2023:** Highland Ridge RV is recalling 11 units of 2023-2024 Highland Ridge Range Lite Air travel trailers because the trailers may have been manufactured without a secondary emergency exit window - **injury risk**.


 **United States 03 August 2023:** Starcraft RV is recalling 17 units of 2023 Super Lite Maxx travel trailers because the trailers may have been manufactured without a secondary emergency exit window - **injury risk**.


 **United States 02 August 2023:** Hyundai Translead is recalling 2 units of 2022 V/T 53SW Q29485 VI2530154-AFJ Dry Van trailers, equipped with Dexter Smart-Steer 2.0 Axles with bolt-on steering arms, because the steering arm may fracture during certain conditions, such as low speed and high side-loading - **crash risk**.


 **United States 02 August 2023:** Hino Motors Sales USA Inc. is recalling 468 units of 2022-2023 NE7A, NJ7A, NJ7B and NV7A vehicles, equipped with headlights that are recessed in the hood, because the headlight back covers and anti-adjustment caps may have been improperly installed which can result in headlight failure, or the headlights being adjusted incorrectly - **crash risk**.


# Automotive Recall Summary


 **United States 02 August 2023:** Shyft Group is recalling 560 units of 2023 Utilmaster Upfit vehicles because the battery cable connections for the electrical harness may be connected incorrectly causing the circuit protection on the cables to be ineffective - **fire risk**.


 **United States 02 August 2023:** Nova Bus Inc. is recalling 13 units of 2022-2023 LFS battery electric transit buses because the rivnut threaded inserts inside the high-voltage battery may be over-tightened and break which could result in a short circuit - **fire risk**.

 **Canada 01 August 2023:** Kawasaki is recalling 195 units of 2023-2024 Kawasaki Ninja ZX-4 motorcycles because the bolt for the alternator rotor may not have been tightened properly - **crash risk**.


 **Canada 01 August 2023:** Altec Industries is recalling 19 units of 2022-2023 Altec AA Series, Am Series, AN Series, AT Series, DH Series, DL, DM Series, D Series, L45, LR8 Series and TA Series aerial devices and digger derricks because the inverter module may not have proper circuit protection for the AC output - **fire risk**.


 **Canada 01 August 2023:** Daimler Truck North America is recalling 3 units of 2023 Freightliner Business Class M2 buses because the driveshaft could break while driving and cause a sudden loss of power to the wheels - **crash risk**.

 **Canada 01 August 2023:** Kia is recalling 10,758 units of Kia 2023-2024 Seltos, 2023 Soul and 2023 Sportage vehicles because the circuit board in the electric oil pump assembly for the transmission may be damaged - **fire risk**.

 **United States 01 August 2023:** Provan Industries LLC is recalling 8 units of 2021-2023 Bengal TX motorhomes, equipped with certain Onan QG 2800i and Onan QG 2800i EVAP generator sets, because the fuel hose between the fuel filter and Injection Pump Module (IPM)

may not be properly secured which can cause a gas leak - **fire risk**.

 **United States 01 August 2023:** Daimler Trucks North America LLC is recalling 205 units of 2023 Freightliner M2 vehicles because the driveshafts can break under certain loading conditions - **crash risk**.

 **United States 01 August 2023:** SmartPlug Systems, LLC is recalling 1,248 units of 30A Shore Power Inlets because the manganese bronze D-rings may crack or fail when over tightened - **fire risk**.

**Get in touch with one of our Product Recall Specialists for analysis on any of the above recall events.**



**US: +1 305 384 4825**

**APAC: +61 2807 30186**

**UK & EU: +44 20 3284 8844**

*This report (including any enclosures and attachments) has been prepared for the exclusive use and benefit of the addressee(s) and solely for the purpose for which it is provided. Unless we provide express prior written consent, no part of this report should be reproduced, distributed or communicated to any third party. Security Exchange Limited does not accept any liability if this report is used for an alternative purpose from which it is intended. The conclusions and recommendations contained herein are offered for the consideration of the addressee and are based on the information made available at the time of reporting. The addressee is under no obligation to adopt any of the recommended measures and Security Exchange Limited cannot be held liable for any resulting errors or omissions.*