




September 2023




North America


 **Canada 29 September 2023:** Forest River is recalling 4 units of 2023 Coachmen Concord motorhomes because they were incorrectly manufactured with four seat belts, whereas only driver and front passenger seat belts should have been installed - **crash risk**.


 **Canada 29 September 2023:** Nissan is recalling 994 units of 2023 Nissan Ariya vehicles because a momentary over-current could occur in the drive motor which could cause the fail-safe mode to activate and cause a loss of power to the wheels - **crash risk**.

 **United States 29 September 2023:** Forest River Inc. is recalling 50 units of 2024 Coachmen Brookstone, Chaparral, Chaparral Lite and Shasta Phoenix fifth wheel trailers because the affected

vehicles may have been manufactured with an incorrect fuse in the power distribution centre - **fire risk**.

 **United States 29 September 2023:** Forest River Inc. is recalling 370 units of 2021-2024 Coachmen Prism and 2023-2024 Coachmen Concord vehicles because the Federal Placard may indicate incorrect information about the number of seat belts - **crash risk**.


 **United States 29 September 2023:** Forest River Inc. is recalling 6 units of 2024 Salem and Wildwood fifth wheels because these vehicles may be missing a secondary emergency exit - **injury risk**.


 **United States 29 September 2023:** PACCAR Incorporated is recalling 257 units of 2021-2024 Kenworth T280, T380, 2020-2024 Peterbilt 548, 536, 2024 Peterbilt 537 and 2020-2024 Kenworth





Automotive Recall Summary


T480 trucks because the timing of the trailer brake release may be delayed - **crash risk**.


 **United States 29 September 2023:** Precision Circuits Inc. is recalling 176 units of power control systems supplied to Brinkley RV because the power control systems were manufactured with undersized 10-gauge wire instead of 6-gauge wire - **fire risk**.


 **United States 29 September 2023:** Winnebago Industries Inc. is recalling 4,968 units of 2020-2024 Revel motorhomes because the cables near the lithium batteries may contact the battery hold-down brackets which can damage the cables and cause a short circuit - **fire risk**.

 **Canada 28 September 2023:** Fiat Chrysler Automobiles is recalling 64,913 units of 2022-2023 Ram 1500, 2022-2024 Ram 2500 and 2022-2023 Ram 3500 vehicles because a software problem could cause the rearview camera image not to appear on the display - **crash risk**.


 **Canada 28 September 2023:** Polaris is recalling 40 units of 2023 Polaris Ranger XP 1000 and Ranger XP 1000 Crew side-by-side ATVs because the centre brake lines may not have been installed correctly - **crash/fire risk**.


 **Canada 28 September 2023:** Polaris is recalling 2 units of 2023 Polaris RZR Pro R side-by-sides because a defect in the fuel tank could cause it to leak at the seam - **fire risk**.


 **United States 28 September 2023:** Nissan North America Inc. is recalling 9,813 units of 2023 Ariya vehicles because the inverter software may detect a short circuit and shut down the EV system resulting in a loss of drive power - **crash risk**.


 **United States 28 September 2023:** Diamond C Trailer MFG is recalling 2,523 units of 2023-2024 FMAX, SDX and PX trailers equipped with a


spare tire winch because the winch system that secures the spare tire to the trailer may loosen or fail over time - **crash risk**.


 **United States 28 September 2023:** Firefly Integration LLC is recalling 124 units of Multiplex HC Relay Cards because the relays may be damaged which can result in an electrical short circuit - **fire risk**.

 **United States 28 September 2023:** Autocar LLC is recalling 1,131 units of 2022-2023 ACX (Xpeditor) vehicles because the steering column shaft pinch bolt may not have been properly secured - **crash risk**.


 **United States 28 September 2023:** Chrysler is recalling 272,911 units of 2022-2023 Ram 1500, Ram 3500 Cab Chassis with GVWR less than 10,000 lbs., and 2022-2024 Ram 2500 vehicles because the radio software may prevent the rearview image from displaying - **crash risk**.


 **Canada 27 September 2023:** PACCAR is recalling 11 units of 2021-2024 Peterbilt 567 and Peterbilt 579 trucks that have the air tank mounted behind the fuel tank because the U-bolts that attach the air tank to the side of the frame may be too long - **fire risk**.


 **Canada 25 September 2023:** Alliance RV is recalling 12 units of 2023-2024 Alliance RV Paradigm RV trailers because the emergency trailer breakaway switch may not have been wired correctly - **crash risk**.


 **United States 25 September 2023:** Kia America Inc. is recalling 1,730,192 units of 2010-2019 Borrego, 2014-2016 Cadenza, 2010-2013 Forte, Forte Koup, Sportage, 2015-2018 K900, 2011-2015 Optima, 2011-2013 Optima Hybrid, Soul, 2012-2017 Rio, 2011-2014 Sorento and 2010-2011 Rondo vehicles because the Hydraulic Electronic Control Unit (HECU) may experience an electrical short which can result in an engine


compartment fire while parked or driving - **injury risk**.


 **Canada 22 September 2023:** Kia is recalling 113 units of 2023 Kia Forte vehicles because the right-front lower control arm could partially separate from the crossmember due to an improper weld - **crash risk**.


 **United States 22 September 2023:** Forest River Inc. is recalling 46 units of 2024 East to West Tandara and Blackthorn fifth wheels because the rear ladder may not be anchored properly in the rear wall which can allow the ladder to detach - **injury risk**.


 **United States 22 September 2023:** Hyundai Motor America is recalling 1,642,551 units of 2011-2015 Elantra, Genesis Coupe, Sonata Hybrid, 2012-2015 Accent, Azera, Veloster, 2013-2015 Elantra Coupe, Santa Fe, 2014-2015 Equus, 2010-2012 Veracruz, 2010-2013 Tucson, 2015 Tucson Fuel Cell and 2013 Santa Fe Sport vehicles because the Anti-Lock Brake System (ABS) module may leak brake fluid internally and cause an electrical short which can result in an engine compartment fire while parked or driving - **injury risk**.


 **United States 22 September 2023:** Hyundai Motor America is recalling 2,354 units of 2024 Kona vehicles because the seat belt assemblies in the right and left rear seats may not function properly - **injury risk**.


 **United States 22 September 2023:** Kia America Inc. is recalling 3,866 units of 2023 Forte vehicles because the right front lower control arm may have been improperly welded which can cause it to fail - **crash risk**.


 **Canada 21 September 2023:** PACCAR is recalling 10 units of 2022-2024 Kenworth T480 and 2020 Peterbilt 537 and 548 trucks because the trailer brakes may release too slowly when the brake pedal is released - **crash risk**.


 **Canada 21 September 2023:** Rolls-Royce is recalling 148 units of 2021-2023 Rolls-Royce Ghost vehicles because the glass panel on the instrument cluster could break in a crash - **injury risk**.


 **Canada 21 September 2023:** Subaru is recalling 202 units of 2023 Subaru Ascent, Impreza, Legacy and Outback vehicles because the bolts that attach the driveshaft centre support brace could loosen which could cause the front end of the driveshaft to separate - **crash risk**.


 **Canada 21 September 2023:** BMW is recalling 93 units of 2023 BMW 7 Series and I7 vehicles because the connection between the windshield wiper motor and windshield wipers could loosen and slip - **crash risk**.


 **United States 21 September 2023:** BMW of North America LLC is recalling 1,305 units of 2021-2023 Rolls-Royce Ghost vehicles because the single-layer tempered glass protecting the instrument cluster may break in a crash - **injury risk**.


 **United States 21 September 2023:** Subaru of America Inc. is recalling 4,311 units of 2023 Outback, Legacy, Ascent and Impreza vehicles because the centre support bolts for the driveshaft may loosen resulting in the disconnection of the front end of the driveshaft - **crash risk**.


 **Canada 20 September 2023:** Tiffin is recalling 21 units of 2016-2023 Tiffin Allegro Bus and 2021 Tiffin Zephyr motorhomes because the wiring for the cooktop may not be grounded - **injury risk**.


 **Canada 20 September 2023:** General Motors is recalling 8 units of 2023 Cadillac Escalade, Chevrolet Suburban, Chevrolet Tahoe and GMC Yukon XL vehicles because a bolt in the rear suspension control arms may not have been manufactured correctly - **crash risk**.


 **United States 20 September 2023:** Wabash National Corporation is recalling 3,711 units of 2009-2024 dry van trailers equipped with a rail-style lift gate because the location of the rear impact guard is too far forward from the rear of the trailer reducing impact protection - **injury risk**.

 **United States 20 September 2023:** BMW of North America LLC is recalling 3,820 units of 2023 740i, 760i xDrive and i7 xDrive60 vehicles because the windshield wipers may fail during certain weather conditions - **crash risk**.

 **United States 20 September 2023:** General Motors LLC is recalling 9,264 units of 2014 Buick Verano and Chevrolet Cruze vehicles because the left and/or right-side roof-rail air bag (RRAB) inflators located on the roof rails above the headliner may rupture at the inflator weld joint - **injury risk**.


 **United States 20 September 2023:** General Motors LLC is recalling 189 units of 2023 Cadillac Escalade, Escalade ESV, Chevrolet Suburban, Chevrolet Tahoe, GMC Yukon and Yukon XL vehicles because the rear suspension outer control arm bolts may not have been properly heat-treated which can cause the bolts to break - **crash risk**.


 **Canada 18 September 2023:** Fiat Chrysler Automobiles is recalling 3 units of 2023 Dodge Durang Pursuit vehicles because the transmission shifter could slip out of the Drive position while driving - **crash risk**.


 **Canada 18 September 2023:** Fiat Chrysler Automobiles is recalling 1,051 units of 2022-2023 Jeep Gladiator and Wrangler vehicles, equipped with a manual transmission, because a problem with the gear sensor (AGS) could cause the rearview camera not to work and the backup lamps not to turn on when backing up - **crash risk**.


 **United States 18 September 2023:** Hyundam Industrial is recalling 183,323 units of


fuel pumps The impeller inside the fuel pump may deform which can cause fuel pump failure - **crash risk**.


 **United States 18 September 2023:** Chrysler is recalling 523 units of Mopar Gear Position Sensors and Transmission Assemblies because when the sensors or transmission assemblies are installed into a vehicle, the rearview camera may fail to display the rearview image and the reverse lights may not illuminate when the vehicle is placed in reverse - **crash/injury risk**.

 **United States 18 September 2023:** Chrysler is recalling 6,298 units of 2022-2023 Jeep Wrangler and Gladiator vehicles equipped with a manual transmission because the rearview camera may fail to display the rearview image and the reverse lights may not illuminate when the vehicle is placed in reverse - **crash/injury risk**.


 **United States 18 September 2023:** Chrysler is recalling 125 units of 2023 Dodge Durango Pursuit vehicles equipped with an instrument panel mounted shifter, because the shifter may experience an interference with the shifter boot and come out of gear while driving which can result in a sudden loss of drive power - **crash risk**.


 **Canada 15 September 2023:** Spartan Fire is recalling 95 units of 2022-2024 KME Panther and 2022-2024 Spartan FC-94, Gladiator and Metro Star emergency vehicles because the inversion valve in the air brake system may not work properly - **crash/injury risk**.


 **United States 15 September 2023:** Winnebago Industries Inc. is recalling 5,369 units of 2022 Ekko, 2020-2022 Minnie Winnie, Spirit, 2020-2022 View, Navion and 2020-2021 Vita and Porto motorhomes because an incorrect hitch label was installed which can lead to overloading of the vehicle - **crash risk**.


 **United States 15 September 2023:** Forest River Inc. is recalling 39 units of 2024 Palomino


hardside, softside and real-lite truck campers because an unnecessary charge line may have been connected to the lithium battery - **fire risk**.


 **United States 15 September 2023:** Kia America Inc. is recalling 83,667 units of 2019 Sorento vehicles because due to a manufacturing error, water may leak into the rearview camera which can cause the rearview camera image not to appear on the display - **crash risk**.


 **United States 14 September 2023:** Altec Industries Inc. is recalling 53 units of 2004-2023 DL42 and DL45 Digger Derricks because the incorrect hydraulic load holding valve may have been installed which can cause the winch to lower uncontrollably and the load to fall - **injury risk**.


 **United States 14 September 2023:** Gillig LLC is recalling 223 units of 2022-2023 Low Floor transit buses because the driveshaft fasteners may have been improperly tightened after service repairs allowing the driveshaft to detach - **crash risk**.


 **Canada 13 September 2023:** Ford is recalling 155 units of 2023 Ford Edge vehicles because the right headlamp may not have been manufactured correctly - **crash risk**.


 **United States 13 September 2023:** Kia America Inc. is recalling 18,224 units of 2018-2021 Stinger vehicles because the fuel control valve plunger may stick inside the high-pressure fuel pump causing over-pressurization and loss of drive power - **crash risk**.


 **United States 13 September 2023:** Toyota Motor Engineering & Manufacturing is recalling 21,781 units of 2023 Tundra and Tundra Hybrid vehicles equipped with a spray-on bed liner accessory because the load carrying capacity modification label states the incorrect load carrying capacity which can result in an overloaded vehicle - **crash risk**.


 **Canada 12 September 2023:** Polaris is recalling 942 units of 2022-2024 Polaris RZR 200 side-by-sides because the steering rack could fail and cause a loss of steering - **crash risk**.


 **United States 12 September 2023:** Kentucky Trailer Manufacturing is recalling 3 units of 2019-2023 (KTSV) XL-12 trailers equipped with Carrier Transicold Supra 950, 950MT and 960 refrigeration units, because the centrifugal clutch may overheat and break apart - **fire risk**.

 **United States 12 September 2023:** Spartan Fire LLC is recalling 660 units of 2021-2024 Gladiator, Metro Star, 2022-2024 FC-94, 2022-2023 KME Panther and 2023 KME Predator emergency vehicles because a defect in the inversion valve may delay park brake engagement which could allow the vehicle to move unintentionally - **crash/injury risk**.

 **United States 11 September 2023:** Hyundai Motor America is recalling 19,272 units of 2021-2022 Genesis G80, GV80 and 2022 Genesis GV70 vehicles because the fuel pump may fail which can result in a loss of drive power - **crash risk**.

 **United States 11 September 2023:** Mercedes-Benz USA LLC is recalling 12,118 units of 2023 GLC300 vehicles because the front tow eye may be inadequately threaded to the crossmember and can detach during towing - **crash/injury risk**.

 **Canada 08 September 2023:** Mercedes-Benz is recalling 1,064 units of 2023 Mercedes-Benz GLC Class vehicles because the recovery eye (tow hook) may not screw into the front crossmember properly - **crash/injury risk**.

 **Canada 08 September 2023:** Moto Guzzi is recalling 63 units of 2023 Moto Guzzi V100 Mandello motorcycles because the rear shock absorber bushings may not have been installed - **crash risk**.



United States 08 September 2023:

Winnebago Industries Inc. is recalling 8,583 units of 2017-2024 Travato motorhomes because the retractable awning may extend unintentionally during transit - **crash risk**.



United States 08 September 2023:

Ford Motor Company is recalling 5,795 units of 2024-2025 Ford E-350, F-650 and F-750 vehicles because the park pawl may not fully engage the park gear due to a casting defect in the transmission - **crash risk**.



United States 08 September 2023:

Ford Motor Company is recalling 2,954 units of 2020-2022 Lincoln Aviator and Ford Explorer vehicles, equipped with 3.0L PHEV engines, because a manufacturing defect in one or more of the high voltage battery cells may result in an internal short circuit and battery failure - **crash/fire risk**.



Canada 07 September 2023:

Fiat Chrysler Automobiles is recalling 753 units of 2023-2024 Alfa Romeo Tonale and 2023-2024 Dodge Hornet plug-in hybrid (PHEV) models because some connections on the integrated dual charging module (IDCM) and high-voltage ground connections may not have been tightened properly - **fire risk**.



United States 07 September 2023:

Midwest Fire Equipment & Repair Company is recalling 19 units of 2022-2023 All-Poly Series Tanker-Pumper fire trucks, equipped with a split-shaft transmission and a Class 1 Es-Key multiplex system, because a software error may cause a shift from road gear to pump gear resulting in a loss of drive power - **crash risk**.



United States 07 September 2023:

BMW of North America LLC is recalling 2,352 units of 2023 BMW XM, 2024 BMW X5 sDrive40i, X5 xDrive40i, X5 M60i, X5 M, X5 xDrive50e, X6 xDrive40i, X6 M60i, X6 M, X7 xDrive40i, X7 M60i and Alpina XB7 vehicles because the front passenger knee air bag may not deploy as intended - **injury risk**.



United States 07 September 2023:

Chrysler is recalling 4,129 units of 2023-2024 Alfa Romeo Tonale and 2023-2024 Dodge Hornet plug-in hybrid electric vehicles because the 12-volt battery positive cable and/or high voltage connector cable may not be tightened properly which can overheat the electrical connections and result in a fire while parked or driving - **injury risk**.



Canada 06 September 2023:

Airstream is recalling 3 units of 2021-2023 Airstream Base Camp RV trailers because an unused wire for a rooftop air conditioner could separate from its connector - **fire risk**.



Canada 06 September 2023:

Airstream is recalling 3 units of 2023 Airstream Interstate motorhomes because an incorrect fuse may have been installed on the main power cable - **fire risk**.



Canada 06 September 2023:

Polaris is recalling 2 units of 2023 Polaris Sportsman 450 ATVs because the wrong operator warning label may have been installed - **injury risk**.



United States 06 September 2023:

Volkswagen Group of America Inc. is recalling 8 units of 2019 Jetta vehicles because the instrument cluster may not provide an audible warning to let the driver know that the key is still in the ignition when the door is open - **crash risk**.



United States 06 September 2023:


Daimler Trucks North America LLC is recalling 679 units of 2024 Thomas Built Buses SAF-T-Liner C2 school buses because the electrical cables for the air conditioning (AC) may not be installed properly which can allow the electrical connection to overheat - **fire risk**.





United States 06 September 2023:


Ducati North America is recalling 842 units of 2018-2020 XDiavel S and XDiavel Standard motorcycles because the side stand bracket may fail causing the side stand to open while riding and resulting in


an unexpected engine shutdown - **crash/injury risk**.


 **Canada 05 September 2023:** PACCAR is recalling 4 units of 2023 Peterbilt 220 trucks because the driveshaft could break while driving and cause a sudden loss of power to the wheels - **crash risk**.

 **Canada 05 September 2023:** PACCAR and/or Cummins is recalling 126 units of 2022-2024 Kenworth T280, T380, T480 and 2023-2024 Peterbilt 537 and 548 trucks because the remote fuel filter hoses may have been damaged during production - **crash/fire risk**.


 **United States 05 September 2023:** PACCAR Incorporated is recalling 871 units of 2023-2024 Kenworth T280, T380, T480, Peterbilt 536, 537 and 548 trucks because the remote Stage 2 fuel filter hoses may have been damaged during production allowing the hoses to leak or disconnect - **fire risk**.


 **United States 05 September 2023:** PACCAR Incorporated is recalling 21 units of 2023 Kenworth K270, K370 and Peterbilt 220 trucks because the driveshafts can break under certain loading conditions - **crash risk**.


 **United States 05 September 2023:** Covercraft Industries LLC is recalling 99 units of Covercraft seat covers and Covercraft Precision Fit seat covers, designed to fit 2021-2023 Toyota Sienna, 2018-2022 Ford Ecosport and 2018-2020 Buick Envision vehicles, because the outboard panel of the seat cover may have been manufactured with incorrect thread which can result in the side-seat air bag deploying incorrectly - **injury risk**.


 **United States 05 September 2023:** Wilson Trailer Company is recalling one 2024 DWH-750 Pacesetter Grain trailer, equipped with a Tire Pilot Plus tire pressure regulation system (TPRS), because all 8 tires may experience a loss of tire


pressure while driving faster than 45 mph - **crash risk**.


 **Canada 01 September 2023:** Kia is recalling 10,587 units of 2022-2023 Kia Sorento vehicles because the rearview camera mounting clips could fail - **crash risk**.


 **Canada 01 September 2023:** Porsche is recalling 501 units of 2023 Porsche Taycan, Taycan Cross Turismo, Taycan Cross Turismo Turbo and Taycan Turbo vehicles because the high-voltage battery may not be sealed properly - **fire risk**.

 **Canada 01 September 2023:** Volkswagen is recalling 234 units of 2023 Audi RS E-Tron GT vehicles because the high-voltage battery may not be sealed properly - **fire risk**.

 **Canada 01 September 2023:** Polaris is recalling 172 units of Polaris 2023 RZR PRO XP, 2023 RZR PRO XP 4, 2024 RZR XP and 2024 RZR XP 4 side-by-sides because the front brake lines may be routed incorrectly - **crash risk**.

 **United States 01 September 2023:** Forest River Inc. is recalling 2,994 units of 2022 Della Terra Travel Trailers and Silver Lake travel trailers because the sidewall extrusion may not have been properly installed which can cause the aluminium siding to detach - **crash/injury risk**.

 **United States 01 September 2023:** Airstream Inc. is recalling 58 units of 2021-2023 16' Basecamp and 20' Basecamp travel trailers manufactured without an air conditioner, because the 12-gauge wire for future air conditioner installation was not properly terminated inside the junction box - **injury risk**.

 **United States 01 September 2023:** Forest River Inc. is recalling 66 units of 2024 Sabre fifth wheels because the Federal Placard indicates an incorrect cargo carrying capacity (CCC) and dry



Automotive Recall Summary

weight which can result in an overloaded vehicle -
crash risk.



United States 01 September 2023: Porsche Cars North America Inc. is recalling 4,777 units of 2023 Taycan, Taycan 4S, Taycan Turbo S, Taycan Turbo, Taycan GTS, Taycan 4 Cross Turismo, Taycan 4S Cross Turismo, Taycan Turbo S Cross Turismo, Taycan Turbo Cross Turismo and Taycan GTS Sport Turismo vehicles because the high-voltage battery may have an insufficient amount of sealant which can allow liquid to accumulate in the battery - fire risk.



United States 01 September 2023: Volkswagen Group of America Inc. is recalling 1,899 units of 2023 Audi RS E-Tron GT and E-Tron GT vehicles because the high-voltage battery may have an insufficient amount of sealant.

Get in touch with one of our Product Recall Specialists for analysis on any of the above recall events.



US: +1 305 384 4825

APAC: +61 2807 30186

UK & EU: +44 20 3284 8844

This report (including any enclosures and attachments) has been prepared for the exclusive use and benefit of the addressee(s) and solely for the purpose for which it is provided. Unless we provide express prior written consent, no part of this report should be reproduced, distributed or communicated to any third party. Security Exchange Limited does not accept any liability if this report is used for an alternative purpose from which it is intended. The conclusions and recommendations contained herein are offered for the consideration of the addressee and are based on the information made available at the time of reporting. The addressee is under no obligation to adopt any of the recommended measures and Security Exchange limited cannot be held liable for any resulting errors or omissions.