


Security Exchange Automotive Recall Summary: December, 2021



North America



Recall Summary

United States 29 December 2021: PACCAR Incorporated is recalling 1,107 units of 2016-2022 Peterbilt 567, 579, 2021-2022 Peterbilt 536, 2017-2021 Kenworth T880, 2016-2022 Kenworth T680, 2018-2020 Kenworth T440, 2020 Kenworth T270 and 2021 Kenworth T280 vehicles because the methane detection system will not function if the system loses power - **injury/fire risk**.

United States 28 December 2021: Hyundai Motor America is recalling 7144 units of 2022 Santa Fe HEV and Santa Fe PHEV vehicles because the instrument cluster liquid-crystal display (LCD) may invert the image on the screen upon vehicle start up, making the display illegible - **crash risk**.

United States 28 December 2021: Hyundai Motor America is recalling 26,413 units of 2020-2021 Santa Fe, 2021 Sonata and Elantra vehicles because during manufacturing, the windshield may not have been properly bonded to the vehicle allowing it to detach in a crash - **injury risk**.

Canada 27 December 2021: Hyundai is recalling 1,893 units of 2021 Hyundai Santa Fe and Sonata vehicles because the windshield may not be properly attached - **injury risk**.

United States 27 December 2021: Mercedes-Benz USA LLC is recalling 1,239 units of 2022 EQS450, S500 and S580 vehicles because the communication module software may restrict or disable the emergency call system (eCall) - **injury risk**.

United States 23 December 2021: Toyota Motor Engineering & Manufacturing is recalling 151 units JTEKT power steering gear assembly service parts for 2007-2021 Tundra and 2008-2022 Sequoia because the power steering gear assembly may have been manufactured incorrectly which can result in an oil leak - **crash risk**.

United States 23 December 2021: Crysteel Manufacturing Inc. is recalling 261 units of Marathon Telescoping Dump Cylinders with a Black Armor finish because the telescopic-style hydraulic cylinder may fail and detach from the hoist cradle - **injury/crash risk**.

Canada 23 December 2021: Clek is recalling 398 units of 2019-2021 Clek Liing and 2020-2021 Liingo infant car

seats because the warning labels on the seat cover or headrest insert may bubble or lift at the edges - **injury risk**.

Canada 23 December 2021: Bugatti is recalling one 2021 Bugatti Chiron vehicles because the rear tires could crack - **crash risk**.

United States 23 December 2021: Daimler Trucks North America LLC is recalling 25,734 units of 2018 Freightliner Custom Chassis XBP, 2017-2020 XBR, 2017-2022 XBS, 2016-2019 XCL, 2016-2023 XCM, 2017-2021 XCP, 2016-2023 XCR and 2017-2023 XCS recreational vehicle chassis because the rear mounted Power Distribution Module (PDM) may have internal damage which could result in the rear marker lights, brake lights, or turn signals not functioning - **crash risk**.

Canada 22 December 2021: Alamo Group is recalling 5 units of 2019-2021 Old Dominion Brush DLC800TM, LCT450, LCT600 and LCT650 trailers because the emergency trailer breakaway switch may not be wired correctly - **crash risk**.

Canada 22 December 2021: Cummins is recalling 24 units of 2019-2021 Spartan Gladiator and 2019-2021 Spartan Metro Star fire trucks because the fuel tubes between the fuel rail and the injectors may crack and create a fuel leak - **fire risk**.

United States 22 December 2021: General Motors LLC is recalling 4,271 units of 2010-2013 Buick Lacrosse, 2012-2013 Buick Regal and 2013 Chevrolet Malibu vehicles because these vehicles may have rear toe links that received an improper amount of electrocoating (e-coat) corrosion protection which could cause the e-coat to become brittle and break away when contacted by road debris. Over time, the e-coat may chip away, exposing the metal toe link and making it more susceptible to corrosion. Corrosion may eventually cause the toe link to thin and ultimately fracture - **crash risk**.

United States 22 December 2021: Alamo Group Inc. Alamo is recalling 31 units of 2012-2021 Schwarze A7 CNG, A8 CNG and A9 CNG street sweepers mounted on Freightliner M2-112 chassis and equipped with a horizontal exhaust system because lightweight debris, such as leaves, may build up in front of the sweeping head and accumulate

North America



Recall Summary

against the chassis exhaust system - **fire risk**.

United States 21 December 2021: Tesla Inc. is recalling 356,309 units 2017-2020 Model 3 vehicles because the rear-view camera cable harness may be damaged by the opening and closing of the trunk lid, preventing the rear-view camera image from displaying - **crash risk**.

United States 21 December 2021: Tesla Inc. is recalling 119,009 units of 2014-2021 Model S vehicles because the front trunk latch assembly may be misaligned, preventing the secondary hood latch from engaging - **crash risk**.

United States 21 December 2021: Chrysler LLC is recalling 7 units of 2022 Jeep Wagoneer and Grand Wagoneer vehicles because the radio software may prevent the rear-view image from displaying - **crash risk**.

Canada 20 December 2021: Polaris recalled 4,501 units of 2020-2021 Bobcat UV34, 2020-2021 Bobcat UV34 XL, 2020 Gravely Atlas JSV 3400, 2020-2021 Polaris Ranger 1000, 2020-2021 Polaris Ranger 1000 Crew, 2020-2021 Polaris Ranger XP 1000 and 2020-2021 Polaris Ranger XP 1000 Crew UTV's because the accelerator pedal may not return when it is released - **crash risk**.

United States 20 December 2021: Daimler Trucks North America LLC is recalling 2 units of 2022 Thomas Built Minotour School Buses built on a Ford chassis because the driver may be able to release the parking brake and shift into a drive gear while the wheelchair lift is deployed - **injury risk**.

United States 20 December 2021: Altec Industries Inc. is recalling 150 units of 2017-2021 AN67-E100, AA67-E100, AN67, AA67 and AN55-E88 aerial devices because the hydraulic plumbing to the lift cylinders of the lower and upper booms could be connected incorrectly, allowing the boom to overextend - **injury risk**.

United States 20 December 2021: Jayco Inc. is recalling 84 units of 2022 Alante Class A and Entegra Coach Vision Class A motorhomes because the main chassis harness may be positioned too close to the exhaust manifold, causing the wiring to melt - **crash risk**.

United States 20 December 2021: Heartland Recreation

Vehicles LLC is recalling 41 units of 2022 Sundance travel trailers because the Federal and Certification labels may indicate incorrect tire information - **crash risk**.

United States 20 December 2021: Cruiser RV is recalling 110 units of 2021-2022 Shadow Cruiser and 2022 Twilight travel trailers because the Federal and Certification labels may indicate incorrect tire information - **crash risk**.

United States 20 December 2021: Clek Inc. expanded an earlier recall to include an additional 596 units of Liing model LG19U1 and Liingo model number LGO20U1 infant child seats because the labels on the seat cover or infant insert may bubble up, allowing the labels to come apart into small pieces - **injury risk**.

United States 20 December 2021: Crane Carrier Company is recalling 25 units of 2019-2021 LET2 vehicles because the fuel tubes between the fuel rail and the injector for cylinders 4, 5 and 6 may be susceptible to cracking, resulting in a high-pressure fuel leak - **fire risk**.

United States 20 December 2021: Van Hool N.V. is recalling 139 units of 2020-2021 CX45, TX45 and 2021 TDX25 vehicles because the fuel tubes between the fuel rail and the injectors for cylinders four, five, and six may fatigue and crack which can result in a high pressure fuel leak - **fire risk**.

United States 18 December 2021: KZRV L.P. is recalling 21 units of 2022 KZRV Connect travel trailers because the propane supply line, routed through the wheel well, may be damaged by road debris - **fire risk**.

Canada 17 December 2021: Forest River is recalling 6 units of 2021-2022 Forest River Cardinal RV trailers because the generator compartment may not be sealed properly - **death/injury risk**.

Canada 17 December 2021: General Motors is recalling 14 units of 2019-2021 Chevrolet Silverado and 2019-2021 GMC Sierra trucks because the spare tire has a smaller diameter than the tires on the truck. As a result, the antilock brake system (ABS) may not work properly on certain road surfaces when the spare tire is installed on a rear wheel position - **crash risk**.

North America



Recall Summary

Canada 17 December 2021: Ford is recalling 214 units of 2021 Ford Bronco and 2021 Ford Ranger vehicles equipped with adaptive cruise control (ACC) because there could be a problem with the front radar module - **crash risk.**

Canada 17 December 2021: Ford is recalling 3 units of 2021 Ford Mustang vehicles because there may be a problem with the side curtain airbag inflators - **crash risk.**

Canada 17 December 2021: Ford is recalling 194 units of 2022 Ford Maverick and 2021-2022 Mustang Mach-E vehicles because the rear seat belt buckles could detach from the floor in a crash - **injury risk.**

Canada 17 December 2021: Micro Bird is recalling 773 units of 2006-2022 Micro Bird G5 Commercial Bus because the fold-away seat was placed next to the emergency exit window - **crash risk.**

Canada 17 December 2021: Ford is recalling 40,362 units of 2021 Ford F-150 trucks because the insulation under the truck may loosen and damage the driveshaft - **injury/crash risk.**

United States 17 December 2021: Corp. Micro Bird Inc. is recalling 75 units of 2013-2021 G5 transit buses because the fold-away seat, adjacent to a side emergency exit, may obstruct access to the emergency exit release handle - **injury risk.**

United States 17 December 2021: Forest River Inc. is recalling 111 units of 2020-2022 Cardinal fifth wheel recreational vehicles because the generator compartment may not be sealed properly, allowing carbon monoxide to enter the vehicle - **injury/death risk.**

United States 17 December 2021: Mercedes-Benz USA LLC is recalling certain 2021 AMG GLB35, 2019-2020 A220 and 2020 GLB250 vehicles because the integral carrier that supports the front axle may corrode, causing it to fail - **crash risk.**

United States 17 December 2021: Mercedes-Benz USA LLC is recalling one 2020 CLA250 vehicle because the power supply connection to the electric power steering may have been contaminated with melted adhesive which can cause the power steering assist to fail while driving -

crash risk.

United States 16 December 2021: Terex Advance Mixer Inc. is recalling 1,016 units of 2016-2022 Front Discharge Mixer trucks because the fuel tubes between the fuel rail and the injectors for cylinders four, five, and six may fatigue and crack, which can result in a high pressure fuel leak - **fire risk.**

United States 16 December 2021: General Motors is recalling 626 units of 2019-2021 GMC Sierra 1500 and Silverado 1500 vehicles because the 17" spare tire provided with the vehicle is not compatible for use with the accessory wheels which can cause the anti-lock brake system (ABS) to not function properly under certain conditions - **crash risk.**

Canada 16 December 2021: Mercedes-Benz is recalling 5,883 units of 2019-2021 Mercedes-Benz Sprinter vehicles because they could roll-away after placing the transmission in the "P" (Park) position if the parking brake is not set - **injury/crash risk.**

Canada 16 December 2021: BMW is recalling 21,679 units of 2018-2021 BMW 2 Series, 2018-2022 BMW X1 and 2018-2022 BMW X2 vehicles because the tell-tale (warning light) for the antilock brake system (ABS) doesn't light up in the instrument cluster when you start the vehicle - **crash risk.**

United States 16 December 2021: Bugatti is recalling 9 units of 2021-2022 Chiron Pur Sport vehicles because after 2,500 miles of usage, the rear tires may develop cracks - **crash risk.**

United States 16 December 2021: Aston Martin The Americas is recalling 1511 units of 2021 DBX vehicles because the vehicles were incorrectly built without headliner foam blocks - **crash risk.**

United States 16 December 2021: Arrow Manufacturing Inc. is recalling 21 units of 2019-2021 Ram 4500 and 5500 cab chassis equipped with LiquidSpring Compressible Liquid Adaptive Suspension Systems (C.L.A.S.S.) because the rear brake calliper flexible line may contact a suspension component, causing a brake fluid leak - **crash risk.**

North America



Recall Summary

United States 16 December 2021: Ford Motor Company is recalling 93 units of 2021 Mustang vehicles because the side curtain air bag inflators may have been manufactured with the incorrect amount of compressed gas which can result in improper air bag inflation - **injury risk**.

United States 16 December 2021: Ford Motor Company is recalling 311 units of 2014 Transit Connect vehicles equipped with a Panoramic Fixed-Glass Vista roof because an improper bond may exist between the panoramic roof and the vehicle body which may result in the panel separating from the vehicle - **injury/crash risk**.

United States 16 December 2021: Ford Motor Company is recalling 57,591 units of 2018 F-150 vehicles with manual and power release tailgates because the tailgate latches may unlatch unexpectedly while driving - **crash risk**.

United States 16 December 2021: Ford Motor Company is recalling 184,698 units of 2021-2022 F-150 vehicles because the underbody heat and noise insulators may loosen and contact the aluminium driveshaft which could damage the driveshaft and cause it to fracture - **crash risk**.

United States 16 December 2021: Ford Motor Company is recalling 5,456 units of 2022 Maverick vehicles because the fuel tank may have been damaged by drill holes during the installation of the spray-in bed-liner - **fire risk**.

United States 16 December 2021: Ford Motor Company is recalling 839 units of 2021 Ranger and Bronco vehicles because the cruise control radar module was misaligned during production - **crash risk**.

United States 16 December 2021: Ford Motor Company is recalling 4,548 units of 2020 Transit vehicles equipped with All Wheel Drive (AWD) because the bolts that attach the rear driveshaft to the transfer case may become loose or damaged which can result in separation of the driveshaft from the transfer case - **crash risk**.

United States 15 December 2021: Daimler Vans USA LLC is recalling 48,400 units of 2019-2021 Mercedes-Benz Sprinter and Freightliner Sprinter vehicles because a software error in the park lock system may allow the vehicle to move after the gear selector has been placed in the Park 'P' position without the parking brake applied - **crash risk**.

United States 15 December 2021: Motor Coach Industries is recalling 1,125 units of 2019-2022 D4000 ISTV, D4500, 2021 D4000, D4520, 2020-2021 D4505, D4005, 2020-2022 D45CRTLE and 2019-2021 J4500 vehicles equipped with certain Cummins X12 diesel engines because the fuel tubes between the fuel rail and the injectors for cylinders four, five, and six may fatigue and crack, which can result in a high pressure fuel leak - **fire risk**.

Canada 15 December 2021: Bentley is recalling 225 units of 2021 Bentley Bentayga, 2021-2022 Bentley Continental GT and 2021-2022 Bentley Flying Spur vehicles because the owner's manual doesn't properly describe how the passenger-front airbag works when the "Passenger Airbag On" light is on - **injury risk**.

United States 15 December 2021: Daimler Vans USA LLC is recalling 48,400 units of 2019-2021 Mercedes-Benz Sprinter and Freightliner Sprinter vehicles because a software error in the park lock system may allow the vehicle to move after the gear selector has been placed in the Park 'P' position without the parking brake applied - **crash risk**.

United States 15 December 2021: Bentley Motors Inc. is recalling 3,777 units of 2021-2022 Bentayga, Continental GT, Flying Spur and Continental GT Convertible vehicles because the owner's manual incorrectly states that the air bag system will not deploy when the "Passenger Airbag On" symbol is illuminated - **injury risk**.

United States 14 December 2021: Shyft Group is recalling 143 units of 2020-2023 Spartan RV Chassis K3 vehicles. The fuel tubes between the fuel rail and the injectors for cylinders four, five, and six may fatigue and crack, which can result in a high pressure fuel leak - **fire risk**.

United States 14 December 2021: Tourig is recalling one 2017 Mercedes-Benz Sprinter vehicle, equipped with a Multiplex G9 unit used for controlling equipment and accessories in the motorhome because excessive voltage may cause the components on the board to become damaged - **fire risk**.

United States 14 December 2021: BorgWarner is recalling 331 units of Delphi Aftermarket Tie Rod assemblies because the inner tie rod assembly may have been manufactured incorrectly which can allow the tie rod to

North America



Recall Summary

detach from the steering rack - **crash risk.**

United States 14 December 2021: Lion Electric Company is recalling 170 units of 2017-2021 LionC school buses because a 12V circuit breaker switch may fail, causing a loss of braking and steering assist - **crash risk.**

United States 13 December 2021: Southeast Toyota Distributors LLC is recalling 78 units of 2022 Toyota 4Runner vehicles because the driver's side high beam may be inoperable after the installation of accessory fog lights - **crash risk.**

United States 13 December 2021: Autocar LLC is recalling 251 units of 2021-2022 Xpeditor vehicles because the GPS module may have been improperly mounted under the dashboard and could come loose or disconnect entirely - **crash risk.**

United States 13 December 2021: Daimler Trucks North America LLC is recalling 2,843 units of 2020-2022 Western Star 4700, 2019-2022 Freightliner 114SD, 2021-2022 Western Star 49X, Freightliner Cascadia P4, 2022 Western Star 47X, 2021 Western Star WF110, 2020 Western Star WJ121 and 2019-2021 FCCC XCP Chassis vehicles because the fuel tubes between the fuel rail and the injectors for cylinders four, five, and six may fatigue and crack, which can result in a high pressure fuel leak - **fire risk.**

Canada 13 December 2021: Yamaha is recalling 543 units of 2021 Yamaha Wolverine RMAX2 and Wolverine RMAX4 UTVs because the wire harness may not have been routed correctly near the passenger footrest - **fire risk.**

Canada 13 December 2021: Cummins is recalling 394 units of 2020-2022 Freightliner 114SD and Cascadia, 2020-2022 Freightliner Custom Chassis XC Chassis, 2020-2022 Western Star 4700, 47X and 49X trucks because the fuel tubes between the fuel rail and the injectors may crack and create a fuel leak - **fire risk.**

United States 13 December 2021: Mercedes-Benz USA LLC is recalling 139 units of 2019 AMG G63, C300, E300, G550, AMG GT63, AMG GT53, 2019-2020 A220, GLA250, GLC300, 2016 C300, 2020 AMG A35, AMG C43, AMG C63, CLA250, E350, E450, GLB250, GLE450,

GLS450, GLS580, S560 and SL550 vehicles equipped with a gasoline engine because during the manufacturing process, particles may have been trapped between the fuel rail and injectors which can cause a fuel leak - **fire risk.**

United States 13 December 2021: Spartan Fire LLC is recalling 114 units of 2019-2022 Gladiator and MetroStar vehicles because the fuel tubes between the fuel rail and the injectors for cylinders four, five, and six may fatigue and crack, which can result in a high pressure fuel leak - **fire risk.**

United States 13 December 2021: Sutphen Corporation is recalling 1844 units of 2016-2020 Sutphen fire trucks because the fuel tubes between the fuel rail and the injectors for cylinders four, five and six may fatigue and crack which can result in a high pressure fuel leak - **fire risk.**

Canada 10 December 2021: Vicinity Motor Corporation is recalling 4 units of 2021 Vicinity VI30 transit buses because a problem with the steering system may cause excessive forces when the steering wheel is turned as far as possible (full lock) - **crash risk.**

United States 10 December 2021: Stainless Tank and Equipment Co. LLC is recalling 87 units of 2019-2020 Wurl Turner trailers because the attachment welds on the bottom of the chassis may develop stress fractures which could result in frame separation - **crash risk.**

Canada 10 December 2021: Nissan is recalling 2,189 units of 2021 Nissan Rogue vehicles because the fuel pump could fail - **crash risk.**

United States 10 December 2021: Kovatch Mobile Equipment Corp is recalling 85 units of 2020-2021 Predator and 2020-2022 Severe Service vehicles because the fuel tubes between the fuel rail and the injectors for cylinders four, five and six may fatigue and crack which can result in a high pressure fuel leak - **fire risk.**

Canada 10 December 2021: Tiffin is recalling 91 units of 2018 2019 2020 2021 2022 Tiffin Allegro Red and 2017 2018 2019 2020 2021 2022 Tiffin Phaeton motorhomes because the tire valve stem extensions for the inner wheels may get damaged by contact with the outer wheels - **crash risk.**

North America



Recall Summary

Canada 10 December 2021: Fiat Chrysler Automobiles is recalling 1,264 units of 2021 Jeep Grand Cherokee vehicles because an incomplete software update could cause one or both of the headlamps not to switch on - **crash risk**.

Canada 10 December 2021: Fiat Chrysler Automobiles is recalling 734 units of 2021 Jeep Wrangler vehicles because the odometer may not display properly after reaching 21,472 km - **crash risk**.

United States 09 December 2021: Chrysler LLC is recalling 2,903 units of 2021 Jeep Wrangler Plug-In Hybrid Electric (PHEV) vehicles because after reaching 13,342 miles, the odometer will no longer display vehicle mileage - **crash risk**.

United States 09 December 2021: Chrysler LLC is recalling 36,929 units of Jeep Grand Cherokee L vehicles equipped with smart lighting modules (SLM) because an incomplete SLM software update may cause one or both headlights to become inoperable - **crash risk**.

United States 09 December 2021: Nissan North America Inc. is recalling 24,793 units of 2021 Rogue vehicles because abnormal wear inside the fuel pump may cause it to overheat and fail - **crash risk**.

United States 09 December 2021: Subaru of America Inc. is recalling 198,255 units of 2019-2020 Ascent, 2020 Legacy and Outback vehicles because a programming error in the Transmission Control Unit (TCU) may allow the clutch to engage before the drive chain is completely clamped - **crash risk**.

United States 09 December 2021: Subaru of America, Inc. is recalling 1,305 units of 2020 Ascent vehicles because due to an incorrect tapered hole in the housing, the front tie rod ends may not fit properly - **crash risk**.

United States 09 December 2021: Nissan North America Inc. is recalling 425 units of 2022 Frontier vehicles because the seat belt bracket mounting bolts on the left-rear seat may have been incorrectly tightened - **injury risk**.

United States 09 December 2021: Prevost Car Inc. is recalling 201 units of 2020-2022 X3 Commuter and X3 Coach buses because the front ceiling panel may come loose and fall - **crash/injury risk**.

United States 09 December 2021: Autocar LLC is recalling 1,001 units of 2019-2022 Xpeditor and 2020-2022 Legend vehicles because the fuel tubes between the fuel rail and the injectors for cylinders four, five and six may fatigue and crack which can result in a high pressure fuel leak - **fire risk**.

United States 09 December 2021: Mack Trucks Inc. is recalling 20,668 units of 2008-2019 TerraPro (MRU) and 2019-2022 TerraPro (TE) vehicles because a brake control valve air leak into the attached exhaust hose can create excessive back pressure, causing the parking brake to release unexpectedly - **crash risk**.

United States 09 December 2021: E-One Incorporated is recalling 1440 units of 2019-2021 Cyclone 2, Quest 2, 2020-2021 Typhoon N, 2020 Typhoon and 2021 Cyclone N vehicles because the fuel tubes between the fuel rail and the injectors for cylinders four, five and six may fatigue and crack which can result in a high pressure fuel leak - **fire risk**.

Canada 09 December 2021: Cummins is recalling 19 units of 2020-2021 E-One ARFF and 2019-2021 E-One Cyclone II fire trucks because the fuel tubes between the fuel rail and the injectors may crack and create a fuel leak - **fire risk**.

Canada 09 December 2021: Audi is recalling 48,146 units of 2018-2022 Audi Q5 and SQ5 vehicles because if you spill liquid on the rear seat, or drive through heavy rain or deep water, the gateway control module could be damaged - **crash risk**.

Canada 09 December 2021: Prevost is recalling 9 units of 2020-2022 Prevost X3-45 Coach buses because the front ceiling panel could become loose and fall inside the bus - **injury/crash risk**.

Canada 09 December 2021: Lion is recalling 238 units of 2017-2022 Lion C school buses because the power cut-off switch for the 12 V electrical system could fail - **crash risk**.

Canada 09 December 2021: Mack is recalling 2,624 units of 2008-2022 Mack Terrapro trucks because the parking brake control valve may wear and leak - **crash risk**.

United States 08 December 2021: Volkswagen Group of America Inc. is recalling 288,991 units of 2021-2022 Q5

North America



Recall Summary

Sportback, SQ5 Sportback, 2018-2022 Q5 and SQ5 vehicles because a liquid spill in the rear seat, or water ingress from an insufficient body seam underneath the vehicle may allow liquid to penetrate the gateway control module causing it to shutdown.

United States 08 December 2021: Daimler Trucks North America LLC is recalling 21 units of 2021-2022 Western Star 4900 vehicles because the steering shaft pinch bolt may not have been properly tightened, allowing the steering shaft to separate from the steering gear - **crash risk**.

United States 08 December 2021: Seagrave Fire Apparatus LLC is recalling certain 2019-2021 Marauder, Attacker and Capitol vehicles equipped with Cummins X12 engines because the fuel tubes between the fuel rail and the injectors for cylinders four, five, and six may fatigue and crack which can result in a high pressure fuel leak - **fire risk**.

United States 08 December 2021: Carson Trailer Inc. is recalling 3 units of 2018-2020 Fun Runner FC20 trailers equipped with Dometic 3-burner cooking stoves because the saddle valve securing bolt may be overtightened, possibly damaging the o-ring seal and causing a continuous gas leak - **fire risk**.

United States 08 December 2021: Daimler Trucks North America LLC is recalling 1,218 units of 2022 Thomas Built Saf-T-Liner C2 school buses because the gas pedal may be misaligned and wear a hole into the floor mat which can trap the gas pedal - **crash risk**.

Canada 08 December 2021: Daimler Trucks North America is recalling 18 units of 2021-2022 Western Star 4900 trucks because the steering shaft may not have been properly installed at the base of the steering column assembly - **crash risk**.

United States 07 December 2021: Great Dane Trailers is recalling 3,288 units of 2022 Champion dry van and Everest refrigerated trailers because the wheel hubs may have an insufficient amount of lubrication which could cause the hub bearings to fail - **crash risk**.

United States 07 December 2021: Hyundai Motor America is recalling 2,679 units of 2017-2019 Ioniq electric

vehicles because an unstable electrical ground may cause the vehicle to enter a fail-safe mode with reduced acceleration and power. In certain conditions while in fail-safe mode the vehicle may accelerate after the gas pedal is released - **crash risk**.

Canada 07 December 2021: Spartan is recalling 6 units of 2021-2022 Spartan Gladiator and Metro Star emergency vehicles because there may be a defect in the rear axle drive pinion that could cause it to break - **crash risk**.

United States 06 December 2021: Dennis Eagle Inc. is recalling 22 units of 2017-2021 Elite and Proview vehicles because the instrument cluster warning light may falsely indicate that an exterior vehicle light is not illuminated - **crash risk**.

United States 06 December 2021: Winnebago Industries Inc. is recalling 402 units of 2022 Ekko vehicles because the shower and sink drainage system may leak and allow water to infiltrate nearby electrical components which could cause an electrical short - **fire risk**.

Canada 04 December 2021: Clek is recalling 98,922 units of 2014-2021 Clek FLLO and 2012-2021 Clek FOONF child car seats because a child could place their fingers through the crotch buckle opening and pick at the foam seat cushion - **injury risk**.

Canada 03 December 2021: Dynamic Specialty Vehicles is recalling 236 units of 2017 2018 2019 2021 Micro Bird CT-Series Commercial Bus, 2017 2018 2019 Micro Bird G5 Commercial Bus, 2017 2018 2019 2021 Micro Bird MBII Commercial Bus buses altered by Dynamic Specialty Vehicles to carry wheelchair passengers because after the buses were modified, the company didn't apply an altered vehicle label with an updated cargo-carrying capacity - **crash risk**.

Canada 03 December 2021: Acura is recalling 57 units of 2021 Acura RDX vehicles because the left-front axle shaft was not properly heat-treated - **crash risk**.

United States 03 December 2021: Zero Motorcycles Inc. is recalling 45 units of 2022 SR, SR/F and SR/S motorcycles because the incorrect rear brake pads were installed - **crash risk**.

North America



Recall Summary

United States 03 December 2021: Hyundai Motor America is recalling 12 units of 2022 Tucson vehicles because the software installed in the Integrated Central Control Unit (ICU) may be incompatible with the vehicle which could result in inoperative headlights and/or taillights - **crash risk**.

Canada 02 December 2021: Kia is recalling 29 units of 2020-2021 Kia Rio vehicles because the brake master cylinder could fail and cause reduced braking - **crash risk**.

United States 02 December 2021: Hyundai Motor America is recalling 76 units of 2021 Accent vehicles because the brake master cylinder may have been manufactured with sharp edges that can damage the inner oil seal resulting in reduced braking performance - **crash risk**.

United States 01 December 2021: Clek Inc. is recalling 5,504 units of Liing model number LG19U1 and Liingo model number LGO20U1 infant child seats because the labels on the seat cover or infant insert may bubble up allowing the labels to come apart into small pieces - **injury risk**.

United States 01 December 2021: Clek Inc. is recalling 150,599 units of Foonf and Fflo convertible child seats because a child may pick pieces of foam from the foam cushion located under the seat pad - **injury risk**.

United States 01 December 2021: Daimler Vans USA LLC is recalling 98 units of 2021 Mercedes-Benz Sprinter and Freightliner Sprinter vehicles because the front axle fender liner and brake hose may be too close, allowing the fender liner to contact and damage the brake hose - **crash risk**.

United States 01 December 2021: Cummins Inc. is recalling 10,938 units of X12 Diesel Engines because the fuel tubes between the fuel rail and the injectors for cylinders four, five and six may fatigue and crack which can result in a high pressure fuel leak - **fire risk**.

United States 01 December 2021: Kia Motors America is recalling 87 units of 2020-2021 Rio vehicles because the brake master cylinder may have been manufactured with sharp edges that can damage the inner oil seal resulting in reduced braking performance - **crash risk**.

United States 01 December 2021: Daimler Vans USA LLC is recalling 98 units of 2021 Mercedes-Benz Sprinter and Freightliner Sprinter vehicles because the front axle fender liner and brake hose may be too close, allowing the fender liner to contact and damage the brake hose - **crash risk**.

United States 01 December 2021: Daimler Vans USA LLC is recalling 30 units of 2021 Mercedes-Benz Sprinter vehicles because the spring-loaded rear step bolt fasteners were not properly tightened - **crash risk**.

United States 01 December 2021: Volkswagen Group of America Inc. is recalling 10 units of 2022 Audi E-Tron GT vehicles because the retaining ring on the air suspension struts may come loose - **crash risk**.



Contact

Get in touch for support from our global team of Auto Recall Specialists.



auto@securityexchange24.com



+44 (0)1491 683710



www.securityexchange24.com

Emergency

To access emergency support in the event of an incident, call our 24/7 crisis centre.

US: +1 305 384 4825

APAC: +61 2807 30186

UK & EU: +44 20 3284 8844

Training

Security Exchange provides a range of product contamination and recall, tamper and extortion mitigation and response consultancy services for the Contaminated Products Insurance market. In partnering with Salford University Business School, we deliver fully accredited, professional and bespoke industry-based training programmes in food and non-food, automotive, pharmaceutical, consumer goods and environmental management. For further information on these services, please contact us at enquiries@securityexchange24.com.