




SECURITY EXCHANGE



Security Exchange

Automotive Recall Summary: February 2023



North America

Recall Summary

Canada 28 February 2023: Newmar is recalling 61 units of Newmar 2022-2023 Dutch Star Class A Motorhome, Essex Class A Motorhome, King Aire Class A Motorhome, London Aire Class A Motorhome, Mountain Aire Class A Motorhome, New Aire Class A Motorhome and Ventana Class A Motorhome because a software problem in the vehicle control module (ICM) could cause a sudden loss of power - **crash risk**.

United States 28 February 2023: Nissan North America Inc. is recalling 1,063 units of 2023 Ariya vehicles because the steering wheel bolt may have been tightened incorrectly or not installed - **crash risk**.

Canada 27 February 2023: Ford is recalling 55 units of 2023 Ford F-150 trucks because the front axle drive pinion could break and cause the truck to lose power to the front wheels - **crash risk**.

Canada 27 February 2023: Tesla is recalling 71 units of 2023 Tesla Model Y vehicles because the bolts that secure the second-row seat back frames may not have been properly tightened - **injury risk**.

United States 27 February 2023: Tesla Inc. is recalling 3,470 units of 2022-2023 Model Y vehicles because the bolts securing the second-row seat back frames may not have been securely tightened - **injury risk**.

United States 27 February 2023: Royal Enfield North America Limited is recalling 4,891 units of 2017-2021 Himalayan motorcycles because the salt used to treat the roads in the winter may corrode the brake callipers causing a decrease or total loss of brake function - **crash risk**.

Canada 24 February 2023: Ford is recalling 449 units of 2023 Ford Transit vehicles because the heating, ventilation and air conditioning (HVAC) system may not work - **crash risk**.

Canada 24 February 2023: Prevost is recalling 80 units of 2019/2020/2023 Prevost H3-45 Coach and 2019-2023 Prevost H3-45 VIP vehicles because the fire sensor located in the engine compartment could fail - **crash risk**.

Canada 24 February 2023: BMW is recalling 64 units of 2023 BMW S1000RR motorcycles equipped with an optional milled hand brake lever because the fulcrum (pivot)

pin for the brake lever may not have been manufactured correctly which can result in a reduction in brake pressure that can cause reduced braking - **crash risk**.

Canada 24 February 2023: BMW is recalling 36 units of 2023 BMW 3 Series, 2022 4 Series and 2023 i4 vehicles because a programming error in the replacement BDC ECU could cause the automatic door locking function not to work - **injury risk**.

United States 24 February 2023: Xos Inc. is recalling 259 units of 2021-2022 SV05 Stepvan vehicles because the tire and loading information label has an incorrect front gross axle weight rating which could lead to an unintentional overloading of the vehicle - **crash risk**.

United States 24 February 2023: Prevost Car Inc. is recalling 555 units of 2018-2023 H3-45 motor coaches and H3-45 VIP motorhomes and 2019 H3-41 motor coaches because the Automatic Fire Suppression System (AFSS) optical fire sensor positioned in the engine compartment's lower region may corrode and malfunction - **crash/injury risk**.

United States 24 February 2023: Ford Motor Company is recalling 98,550 units of 2004-2006 Ranger vehicles that received replacement front passenger air bag inflators under a previous recall because the replacement frontal passenger air bag inflators may have been installed incorrectly - **injury risk**.

United States 24 February 2023: Ford Motor Company is recalling 240 units of 2023 F-150, Expedition and Lincoln Navigator vehicles because the front axle pinion may not have been heat-treated which can cause it to fracture - **crash risk**.

United States 24 February 2023: Ford Motor Company is recalling 4,804 units of 2023 Transit vehicles equipped with the Special Vehicle Operations Accessory Service Kit #1 or #2 with a High Specification Vehicle Interface Connector because when the accessory kit is installed, the auxiliary wire harness will disable the heating, air-conditioning and ventilation (HVAC) including the defrost and defog systems - **crash risk**.

United States 24 February 2023: BMW of North America LLC is recalling 394 units of 2023 S 1000 RR motorcycles



North America

Recall Summary

because the motorcycle hand brake lever may not function correctly, reducing brake performance - [crash risk](#).

United States 24 February 2023: Gillig LLC is recalling 349 units of 2011-2021 Low Floor 29-foot CNG transit buses because the rear suspension lower control arm may fail - [crash risk](#).

United States 24 February 2023: Thor Motor Coach is recalling 1,836 units of 2018-2021 Hurricane and Windsport recreational vehicles because the driver and front passenger overhead cabinets may detach - [crash/injury risk](#).

Canada 23 February 2023: Navistar is recalling 2,003 units of 2022-2024 International HV and International MV trucks equipped with an automatic transmission because when the engine RPM increases for the stationary power take off (PTO), it can overcome the parking brake if the transmission is in drive or reverse gear - [crash risk](#).

Canada 23 February 2023: Fiat Chrysler Automobiles is recalling 18,163 units of 2021-2023 Dodge Durango vehicles because the rear spoiler could hit the body when opening and closing the liftgate which could damage the spoiler and cause it to detach from the vehicle - [crash risk](#).

Canada 23 February 2023: Fiat Chrysler Automobiles is recalling 7,464 units of 2020-2023 Jeep Gladiator and 2018-2023 Jeep Wrangler because under certain conditions, the clutch pressure plate could overheat and break - [fire/injury risk](#).

United States 23 February 2023: BMW of North America LLC is recalling 120 units 2023 330i, 330i xDrive, M340i, M340i xDrive, M3, 330e, 330e xDrive, 430i Convertible, 430i xDrive, M440i, 2022-2023 430i, 430i xDrive, M440i xDrive, i4 eDrive40 and i4 M50 vehicles because during a service visit, a replacement electronic control unit (ECU) may have been installed with incorrect programming which can cause the automatic door locking (ADL) function to not lock the doors as intended - [injury risk](#).

United States 23 February 2023: Braun Ambulances is recalling 64 units of 2022 Demers ambulances because the rear step of the ambulance may fail under weight due to incorrect welding - [injury risk](#).



United States 23 February 2023: Thor Motor Coach is recalling 1,969 units of 2015-2023 Palazzo recreational vehicles because the front lower cap brackets that support the front fiberglass panel may become loose and detach from the vehicle while in motion - [crash risk](#).

United States 23 February 2023: Navistar Inc. is recalling 27,972 units of 2022-2024 International HV, International MV trucks and 2022-2023 IC Bus TC commercial buses because when the parking brake is applied, the automatic transmission is still in drive or reverse position, and the stationary power take-off (PTO) switch is engaged by the operator, the engine may rev and overcome the parking brake's ability to keep the vehicle from moving - [crash/injury risk](#).

United States 23 February 2023: Fiat Chrysler Automobiles is recalling 69,201 units of 2018-2023 Jeep Wrangler and 2020-2023 Jeep Gladiator vehicles equipped with manual transmissions because the clutch pressure plate may overheat and fracture - [crash risk](#).

United States 23 February 2023: Fiat Chrysler Automobiles is recalling 139,019 units of 2021-2023 Dodge Durango vehicles because the rear spoiler may not be aligned properly with the roof, resulting in damage to the spoiler during liftgate use - [crash risk](#).

United States 23 February 2023: Navistar Inc. is recalling 4,199 units of 2018-2021 International HV, 2019-2021 International RH, 2019-2022 International MV and 2022 International HX vehicles because a software error in the Body Control Module (BCM) may allow the vehicle to overcome the park brake during power-take-off (PTO) operation - [crash/injury risk](#).

Canada 22 February 2023: General Motors is recalling one 2023 Cadillac XT5 vehicle because the right-front axle shaft may not have been manufactured properly - [crash/injury risk](#).

Canada 22 February 2023: Toyota is recalling 794 units of 2022-2023 Toyota Tundra trucks because a software problem could cause the instrument cluster display to go blank while driving - [crash risk](#).

United States 22 February 2023: Lordstown EV Corp is

North America



Recall Summary

recalling 19 units of 2023 Endurance electric pickup trucks because the high-voltage cable between the inverter and motor may experience a fault that causes a loss of drive power and the vehicle cannot be restarted once turned off - **crash risk**.

United States 22 February 2023: Roadtrek Inc. is recalling 54 units of 2021-2022 Zion, Chase, Zion Slumber, Play, Play Slumber, Zion SRT and Play SRT recreational vehicles, equipped with certain SDS2 2-burner drop-in cooktops because the internal aluminium burner tubes that connect to the gas valves may fracture and cause a gas leak - **fire risk**.

United States 22 February 2023: Rivian Automotive LLC is recalling 12,716 units of 2022 R1T and R1S vehicles because a faulty automatic locking retractor (ALR) sensor in the front passenger seat belt system may incorrectly report as ON when it is actually OFF causing the suppression or improper deployment of the air bag - **injury risk**.

United States 22 February 2023: Toyota Motor Engineering & Manufacturing is recalling 8,989 units of 2022-2023 Tundra and Tundra Hybrid vehicles because a software error in the combination meter's electronic control unit (ECU) may cause the Instrument Panel LCD display to go blank - **crash risk**.

United States 21 February 2023: Par Nado Inc. is recalling 1,098 units of 2021-2024 Alto R1713, R1723, F1743, F2114, A2124 and F2414 travel trailers equipped with certain SDS2 2-burner drop-in cooktops because the internal aluminium burner tubes that connect to the gas valves may fracture and cause a gas leak - **fire risk**.

United States 21 February 2023: Nissan North America Inc. is recalling 17 units of 2023 Infiniti QX60 vehicles because the second-row adjustable seat may extend past the intended rear stopper point and may be difficult to move, become stuck, or fail to lock in the correct position - **injury risk**.

Canada 20 February 2023: Jayco is recalling 222 units of 2022-2023 Entegra Coach Accolade, Anthem, Aspire, Esteem, Expanse, Odyssey, Reatta, Reatta XL, Vision, Vision XL, 2022-2023 Jayco Alante Motorhome, Embark, Greyhawk Motorhome, Melbourne, Precept Motorhome,

Redhawk Motorhome, Seneca Motorhome and Solstice motorhomes because the compliance label on certain motorhomes is missing the gross axle weight rating (GAWR) for the rear axle - **crash risk**.

United States 20 February 2023: Polaris Inc. is recalling 163 units of 2022-2023 Slingshot R, Slingshot S with Technology Package 1, Slingshot SL, Slingshot SLR and Slingshot S motorcycles because the alternator may have been improperly heat-treated during manufacturing - **fire risk**.

United States 20 February 2023: Jayco Inc. is recalling 2,467 units of 2022-2023 Entegra Accolade, Accolade XL, Anthem, Aspire, Cornerstone, Emblem, Esteem, Expanse, Expanse LI, Odyssey, Qwest, Reatta, Reatta XL, Jayco Alante, Greyhawk, Greyhawk Prestige, Melbourne, Melbourne Prestige, Precept, Precept Prestige, Redhawk, Redhawk SE, Seneca, Seneca Prestige and Seneca XT recreational vehicles because the certification labels may be missing the rear Gross Axle Weight Rating (GAWR) - **crash risk**.

United States 20 February 2023: Tiffin Motorhomes Inc. is recalling 243 units of 2021-2022 Cahaba recreational vehicles because the rear Sumo Springs may be the wrong size and the front Sumo Springs may have been installed in an incorrect location - **crash risk**.

United States 20 February 2023: Daimler Trucks North America LLC is recalling 60,604 units of 2019-2021 Freightliner 108SD, 114SD, 122SD, Columbia, Coronado, Business Class M2 and 2020 Freightliner Cascadia vehicles because the drag link taper joint may not have been tightened sufficiently and could come loose, resulting in a complete separation of the drag link from the steering arm - **crash risk**.

United States 20 February 2023: Aluminum Trailer Company is recalling 757 units of 2021-2023 Toyhauler and Quest trailers equipped with certain SDS2 2-Burner Drop-in Cooktops because the internal aluminium burner tubes that connect to the gas valves may fracture and cause a gas leak - **fire risk**.

Canada 17 February 2023: Pierce is recalling 15 units of 2018-2023 Pierce Arrow XT, Enforcer, Impel and Velocity

North America



Recall Summary

fire trucks because the hinge peg for the basket handrail on the aerial platform could break - [injury risk](#).

Canada 17 February 2023: BMW is recalling 258 units of 2023 BMW 2 Series, 8 Series and Z4 vehicles because a software problem could allow you to close the windows and roof without the digital key inside the vehicle - [injury risk](#).

Canada 17 February 2023: Hyundai is recalling 6,900 units of 2021-2023 Genesis G80, 2023 Genesis GV60, 2022-2023 Genesis GV70 and 2021-2023 Genesis GV80 vehicles because there may be a problem with the front seat belt pretensioners - [injury risk](#).

United States 17 February 2023: Pierce Manufacturing is recalling 64 units 2018-2023 Velocity, Impel, Enforcer, and Arrow XT 110-foot aerial trucks because when the aerial platform is extended to its maximum angle, the platform mounting bracket may interfere with the basket handrail hinge peg and cause the handrail to detach from the basket - [injury risk](#).

United States 17 February 2023: Daimler Vans USA LLC is recalling 52,993 units of 2019-2020 Mercedes-Benz Sprinter VS30 and Freightliner Sprinter VS30 vehicles because the heating, ventilation and air conditioning (HVAC) blower motor circuit may be inadequate which can allow the wiring harness to overheat - [fire risk](#).

United States 17 February 2023: BMW of North America LLC is recalling 3,193 units of 2023 8 Series Coupe (840i, 840i xDrive, M850i xDrive, M8), 8 Series Convertible (840i, 840i xDrive, M850i xDrive, M8), 8 Series Gran Coupe (840i, 840i xDrive, M850i xDrive, M8, Alpine B8 xDrive), 2 Series Coupe (230i, 230i xDrive, M240i xDrive, M2) and 2022-2023 Z4 sDrive30i, Z4 M40i vehicles because when the digital key is removed from the vehicle, the Electronic Control Unit (ECU) software may still allow the power windows and sunroof to be closed - [injury risk](#).

Canada 16 February 2023: Honda is recalling one 2023 Honda CR-V vehicle because the front passenger's seat frame may not have been properly welded - [injury risk](#).

Canada 16 February 2023: Jayco is recalling 7 units of 2023 Jayco Redhawk Motorhomes because the wrong seat belt brackets may have been installed on the dinette seats -

[injury risk](#).

United States 16 February 2023: Jayco Inc. is recalling 2,845 units of 2019-2023 Entegra Launch, Launch LE, Qwest, Jayco Melbourne, Melbourne Prestige, Terrain and Terrain LE motorhomes because the guide bushing on the parking pawl may fatigue which can cause the parking pawl not to engage and result in a vehicle rollaway - [crash risk](#).

United States 16 February 2023: Nissan North America Inc. is recalling 712,458 units of 2014-2020 Rogue and 2017-2022 Rogue Sport vehicles equipped with a jack-knife style ignition key because the jack-knife key may collapse into a folded position while driving - [crash/injury risk](#).

United States 16 February 2023: Nikola Corporation is recalling 137 units of 2022 TRE BEV vehicles because the shaft locking screw on the brake pedal may be missing or may not be fully threaded which can cause the brake pedal to detach - [crash risk](#).

United States 16 February 2023: Jayco Inc. is recalling 20 units of 2023 Redhawk SE motorhomes because the dinette rear and forward-facing seat belts have the incorrect brackets installed which can cause the brackets to loosen - [injury risk](#).

United States 16 February 2023: Electra Meccanica Vehicles Corp is recalling 428 units of 2021-2023 Solo vehicles because a defect in the motor controller and inverter or the battery controller may cause the electric motor to shut down and cause a sudden loss of drive power - [crash risk](#).

United States 16 February 2023: Continental Tire the Americas LLC is recalling 3 units of General Altimax RT43 because they contain a tire identification number (TIN) that is missing the 3-digit plant code and the 6-symbol manufacturer's identification mark - [crash risk](#).

United States 16 February 2023: Honda is recalling 98 units of 2023 CR-V vehicles because the front passenger seat back frame may not have been welded properly which can cause the seat back position to fail in the event of a crash - [injury risk](#).

United States 16 February 2023: Hyundai Motor

North America



Recall Summary

America is recalling 65,517 units of 2020-2023 Genesis GV80, 2021-2023 Genesis G80, 2022-2023 Genesis GV70 and 2023 Genesis GV60 vehicles because in the event of a crash, the front driver-side and/or passenger-side seat belt pretensioners may explode upon deployment - **injury risk**.

Canada 15 February 2023: PACCAR is recalling 410 units of 2022-2024 Kenworth T280, T380, T480 and Peterbilt 537 and 538 trucks because when the brake pedal is fully applied and released quickly, the pedal plunger could jam or disconnect from the brake valve - **crash risk**.

Canada 15 February 2023: Audi is recalling 78 units of 2022-2023 Audi A8 and S8 vehicles because the occupant protection flap within the passenger-front airbag module may not have been folded properly - **injury risk**.

Canada 15 February 2023: Keystone is recalling 226 units of 2021-2023 Keystone Carbon, Fuzion, Impact and Raptor RV trailers because the fuel station controller could fail - **fire risk**.

Canada 15 February 2023: Jayco is recalling 168 units of 2019-2023 Entegra Coach Launch, Jayco Melbourne, Jayco Melbourne Prestige, Jayco Qwest and Jayco Terrain motorhomes because in certain conditions, the motorhome could roll-away after placing the transmission in the "P" (Park) position if the parking brake is not set - **injury/crash risk**.

United States 15 February 2023: New Flyer of America Inc. is recalling 219 units of 2021-2022 XE35, 2021-2023 XE40 and 2021-2022 XE60 electric buses because one or more battery packs may accumulate liquid in the battery pack enclosure - **fire risk**.

United States 15 February 2023: PACCAR Incorporated is recalling 8,008 units of 2021-2024 Kenworth T280, T380, T480, Peterbilt 536, 537 and 548 vehicles because when the brake pedal is fully applied and then released rapidly, the pedal plunger that connects the brake pedal to the brake valve may become disconnected, causing the service brakes to fail - **crash risk**.

United States 15 February 2023: Tesla Inc. is recalling 362,758 units of 2016-2023 Model S, Model X, 2017-

2023 Model 3 and 2020-2023 Model Y vehicles equipped with Full Self-Driving Beta (FSD Beta) software or pending installation because the FSD Beta system may allow the vehicle to act unsafe around intersections, such as traveling straight through an intersection while in a turn-only lane, entering a stop sign-controlled intersection without coming to a complete stop, or proceeding into an intersection during a steady yellow traffic signal without due caution. In addition, the system may respond insufficiently to changes in posted speed limits or not adequately account for the driver's adjustment of the vehicle's speed to exceed posted speed limits - **crash risk**.

United States 15 February 2023: Keystone RV Company is recalling 5,564 units of 2021-2023 Carbon, Fuzion, Impact and Raptor travel trailers because the fuel station controller may fail - **fire risk**.

United States 15 February 2023: Suzuki Motor USA LLC is recalling 2,552 units of 2022 GSX1300RRQ/ZM2 (Hayabusa) motorcycles because an incorrect position of the front brake master cylinder primary port could cause the port to become blocked and result in a gap between the front brake pad and discs - **crash risk**.

United States 15 February 2023: Volkswagen Group of America Inc. is recalling 12,100 units of 2009-2015 Q7 vehicles because the Gross Axle Weight Rating (GAWR) listed on the certification label is incorrect which can allow the vehicle to be overloaded - **crash risk**.

United States 15 February 2023: Volkswagen Group of America Inc. is recalling 1,047 units of 2022-2023 S8 and A8 vehicles because during air bag assembly, the front-passenger occupant protection flap of the air bag may not have been folded correctly - **injury risk**.

Canada 14 February 2023: BraunAbility is recalling 41 units of 1997-2023 BraunAbility Turny Evo Seat because on vehicles equipped with an aftermarket BraunAbility Turny Evo seat, the optional anchors for attaching a child or booster seat may not have been welded correctly - **injury risk**.

Canada 14 February 2023: Truck Outfitters Canada Inc. is recalling 150 units of 2010-2023 Truck Outfitters Canada Inc. Deck Body and Dump Body vehicles because they

North America

Recall Summary

were built with reflective tape instead of the required reflex reflectors - **crash risk**.

Canada 14 February 2023: Tesla is recalling 20,667 units of 2018-2022 Tesla Model 3, 2016-2023 Model S, 2016-2023 Model X and 2020-2022 Model Y because in certain traffic situations, when the FSD Beta advanced driver assistance feature is engaged, the vehicle may perform manoeuvres that break certain traffic laws if the driver doesn't intervene and take control - **crash risk**.

Canada 14 February 2023: BMW is recalling 3,882 units of 2022-2023 BMW IX and 2023 X1 vehicles because the driver-front airbag may not inflate correctly in a crash - **injury risk**.

Canada 14 February 2023: Daimler Truck North America is recalling 420 units of 2022-2024 Freightliner Business Class M2, Cascadia, 2022-2024 Western Star 4700, 47X and 49X trucks because the tail lamps do not turn on when the daytime running lamps (DRLs) are on - **crash risk**.

United States 14 February 2023: Bendix Commercial Vehicle Systems LLC is recalling 836 units of Intellipark Towing Park Brake Modules (PVM) because the PVM may become stuck and fail to move into the park position when the park switch is activated - **crash risk**.

United States 14 February 2023: BMW of North America LLC is recalling 15,803 units of 2022-2023 iX xDrive40, iX xDrive50, iX M60 and 2022-2023 X1 xDrive28i vehicles because the front driver's air bag may have been manufactured incorrectly and may not deploy as intended during a crash - **injury risk**.

United States 14 February 2023: Subaru of America Inc. is recalling 8,413 units of 2019-2022 Crosstrek Hybrid vehicles because the harness terminal that supplies low-voltage power from the converter to the 12-Volt battery may corrode and break, preventing the 12-Volt battery from charging - **crash risk**.

Canada 13 February 2023: Safari Condo is recalling is recalling 1,098 units of 2021-2024 Safari Condo Alto A-Series, Alto F-Series, Alto R-Series, 2020-2022 Safari Condo LDX, LX, MX, XL Flex and XL Plus RV trailers and motorhomes because the aluminium tubes that connect the



gas valves to the cooktop burners could crack - **fire risk**.

Canada 13 February 2023: Lakota is recalling 10 units of 2019-2023 Lakota Bighorn trailers because the vaulted ceiling over the bed in the gooseneck area wasn't installed correctly - **injury risk**.

Canada 13 February 2023: Ford is recalling 48 units of 2023 Ford Bronco, Explorer and F-150 because there could be a loose bolt inside the transmission - **injury/crash risk**.

Canada 13 February 2023: Ford is recalling 107 units of 2023 Ford Transit vehicles because the fuel tank vent valve may not have been properly welded to the fuel tank - **fire risk**.

Canada 13 February 2023: Ford is recalling 20 units of 2023 Ford F-150 trucks because a problem with the instrument panel cover may cause the passenger-front airbag not to inflate properly in a crash - **injury risk**.

United States 13 February 2023: Lakota Corporation is recalling 445 units of 2019-2023 Bighorn trailers because the trey ceiling above the bed may not have been installed correctly and may detach - **injury risk**.

United States 13 February 2023: Braun Corporation is recalling 153 units of child seat weldments sold as accessory parts to the BraunAbility Turny Seat, because the child restraint lower anchors may have been manufactured with improper welds - **injury risk**.

United States 13 February 2023: Proterra Operating Company Inc. is recalling 274 units of 2020-2022 35" Catalyst, 35" ZX5 and 40" ZX5 vehicles because the windshield wiper motors may operate intermittently or may fail to operate - **crash risk**.

United States 13 February 2023: Subaru of America Inc. is recalling 130 units of 2004-2005 Impreza and WRX vehicles that received replacement front passenger air bag inflators under a previous recall because the replacement air bag inflators may have been installed incorrectly - **injury risk**.

Canada 10 February 2023: Daimler Truck North America is recalling 20,527 units of 2017-2023 Freightliner Cascadia,

North America

Recall Summary

2017-2023 Western Star 47X and 4X trucks because the brake modulator valves could corrode - [crash risk](#).

Canada 10 February 2023: Thor Motor Coach is recalling 39 units of 2022-2023 Thor Motor Coach Rize and Scope motorhomes because the retractable awning could extend on its own while driving - [crash risk](#).

United States 10 February 2023: Gillig LLC is recalling 487 units of SAF Holland suspension torque rods, sold as replacement parts, because they may be incompatible and cause damage to the vehicle wiring harness and certain safety-related circuits such as anti-lock or service brakes, stability control, exterior lighting equipment, power steering or engine and transmission control modules - [crash risk](#).

United States 10 February 2023: Bendix Commercial Vehicle Systems LLC is recalling 10,425 units of Foot Brake Valve Assemblies, model Medium-Duty Vehicle Pedal A, because when the brake pedal is fully applied and then released rapidly, the pedal plunger that connects the brake pedal to the brake valve may become disconnected causing the brakes to fail - [crash risk](#).

United States 10 February 2023: Ford Motor Company is recalling 321 units of 2023 F-150 vehicles because the instrument panel top cover on the passenger-side may prevent the air bag from deploying as intended - [injury risk](#).

United States 10 February 2023: Ford Motor Company is recalling 1,138 units of 2022-2023 F-150, Mustang, Explorer, Bronco and 2023 Lincoln Aviator vehicles equipped with automatic transmissions because the transmission may contain a loose bolt which could prevent the transmission from engaging the park gear, although the gear shifter position may indicate that the vehicle has been shifted to "PARK" - [crash/injury risk](#).

United States 10 February 2023: Ford Motor Company is recalling 1,159 units of 2023 Transit vehicles because the fuel tank grade vent valve may not be properly welded to the fuel tank shell which can result in a fuel leak - [fire risk](#).

United States 10 February 2023: Ford Motor Company is recalling 3,674 units of 2020-2022 Explorer vehicles equipped with a 2.3L engine and 10R60 automatic transmission because an unintentional powertrain control



module (PCM) reset may occur while the vehicle is in motion and result in park system damage - [crash/injury risk](#).

United States 10 February 2023: Nissan North America Inc. is recalling 10,846 units of driver's air bag assemblies, sold as replacement parts, because the resin emblem on the driver's air bag cover may develop cracks and detach during air bag deployment - [injury risk](#).

United States 10 February 2023: Nissan North America Inc. is recalling 404,690 units of 2008-2011 Titan, Frontier, Xterra, Pathfinder, Armada and 2008-2009 Quest vehicles because the resin emblem on the driver's air bag cover may develop cracks and detach during air bag deployment - [injury risk](#).

United States 10 February 2023: Gillig LLC is recalling 1,335 units of 2022-2023 Low Floor transit and shuttle buses because incompatible steering system draglink parts may have been installed during the vehicle assembly process, potentially resulting in long-term damage of the steering system - [crash risk](#).

United States 10 February 2023: Navistar Inc. is recalling 115 units of 2022-2023 IC Bus CE and 2022-2023 IC RE transit buses because the roof panel may have been manufactured with insufficient joint strength - [injury risk](#).

United States 10 February 2023: Columbus Trading-Partners USA Inc. is recalling 31,080 units of Cybex models Aton, Aton Q, Aton M, Aton 2 and Cloud Q rear facing infant seats because the webbing for the front harness adjustment strap, used to snugly adjust the shoulder harness straps onto the infant, may fray which can reduce the strength of the front harness adjustment strap - [injury risk](#).

United States 10 February 2023: Daimler Trucks North America LLC is recalling 70,167 units of 2017-2023 Freightliner Cascadia, 2020-2023 Western Star 49X, 2021-2023 Western Star 47X and 2022 Freightliner 114SD vehicles because the brake modulator valves on the front axle may corrode and cause the vehicle to pull to the affected side during braking initiated by Electronic Stability Control (ESC) or Roll Stability Control (RSC) - [crash risk](#).

United States 10 February 2023: Navistar Inc. is recalling

North America

Recall Summary

12,507 units of 2022-2024 IC Bus CE, 2022-2023 IC CE SBus, IC RE and 2023 EV school buses because the roof panel may have been manufactured with insufficient joint strength - [injury risk](#).

United States 10 February 2023: Thor Motor Coach is recalling 1,557 units of 2021-2023 Rize and Scope camper vans because the retractable awning may extend unintentionally during transit - [crash risk](#).

Canada 09 February 2023: Navistar is recalling 28 units of 2022-2023 IC Bus CE Commercial Bus because the roof panels may not have been attached correctly - [injury risk](#).

Canada 09 February 2023: Navistar is recalling 1,219 units of 2022-2024 IC Bus CE School Bus, 2023 EV School Bus and RE School Bus because the roof panels may not have been attached correctly - [injury risk](#).

Canada 09 February 2023: Fiat Chrysler Automobiles is recalling 7,884 units of 2021-2023 Ram 1500 and Ram 2500 because on certain vehicles equipped with a trailer reverse steering module (TRSCM), the rearview camera image may not appear on the display when backing-up - [crash risk](#).

Canada 09 February 2023: Daimler Truck North America is recalling 27 units of 2021-2023 Freightliner Coronado trucks because the pivot bolt for the foldable upper bunk may not have been properly tightened - [injury risk](#).

United States 09 February 2023: Fiat Chrysler Automobiles is recalling 90 units of 2022 Jeep Compass vehicles because the instrument panel centre cluster display may be insufficiently illuminated and may not appear visible during daytime driving conditions - [crash risk](#).

United States 09 February 2023: Fiat Chrysler Automobiles is recalling 302,067 units of 2021-2023 Ram 2500, 3500, 3500 Cab Chassis and 4500, 5500 Cab Chassis vehicles equipped with a Cummins 6.7L Turbo Diesel engine because an electrical short may occur in the heater grid relay with the ignition on or off - [injury risk](#).

United States 09 February 2023: Fiat Chrysler Automobiles is recalling 1,090 units of Mopar Trailer Reverse Steering Control Modules (TRSCM) because the modules may



prevent the rear-view image from displaying when the vehicle is placed in reverse - [injury/crash risk](#).

United States 09 February 2023: Fiat Chrysler Automobiles is recalling 96 units of Mopar Generation 1 Intake Heater Grid Relays because the relay, when installed on a vehicle, can experience an electrical short with the ignition on or off - [injury risk](#).

United States 09 February 2023: Fiat Chrysler Automobiles is recalling 68,809 units of 2021-2023 Ram 1500 and 2023 Ram 2500 vehicles because the trailer reverse steering control module (TRSCM) may prevent the rear-view image from displaying when the vehicle is placed in reverse - [injury/crash risk](#).

United States 09 February 2023: Subaru of America Inc. is recalling 1,182 units of 2023 Solterra vehicles because the improperly tightened hub bolts may loosen and cause the wheels to detach from the vehicle - [crash risk](#).

United States 09 February 2023: Daimler Trucks North America LLC is recalling 192 units of 2021-2023 Freightliner Coronado vehicles equipped with a foldable upper bunk because the mounting pivot bolts for the upper bunk may not have been tightened properly and may loosen - [injury risk](#).

United States 09 February 2023: Forest River Inc. is recalling 12 units of 2022-2023 Coachmen Galleria, 2023 Coachmen Beyond and 2023 Nova motorhomes, equipped with SDS2 2-Burner Drop-in Cooktops, because the internal aluminium burner tubes that connect to the gas valves may fracture and cause a gas leak - [fire risk](#).

United States 09 February 2023: Shyft Group is recalling 2,336 units of 2022-2024 Spartan RV K1, K2, K3 and K4 motorhome chassis because a vehicle control module software error may cause loss of drive power or loss of key safety functions, such as loss of head lights or windshield wipers - [crash risk](#).

Canada 08 February 2023: Nissan is recalling 13,108 units of 2018-2023 Nissan Leaf because when the temperature is below -10° C, the defroster may not work properly if a user consults the instructions in the owner's manual - [crash risk](#).

North America



Recall Summary

United States 07 February 2023: Newell Coach Corp. is recalling 13 units of 2023 P50 motor coaches because the battery disconnect switch may fail to disconnect the battery when turned to the off position - **injury risk**.

United States 07 February 2023: Maintainer Corporation of Iowa Inc. is recalling 1,120 units of 2019-2023 Maintainer Service Trucks with Hydraulic Telescopic Cranes because during crane operation, if power gets disconnected to the receiver on the Maintainer crane, the crane may continue to move without control of the user - **injury risk**.

United States 07 February 2023: Lippert is recalling 1,043 units of Global latches, used in Lippert series 3500 and 920 entry doors, because the entry door latch may fail and not allow entry or exit - **injury risk**.

United States 07 February 2023: Pleasant Valley Teardrop Trailers LLC is recalling 640 units of 2023 Teardrop TAB 320s and TAB 320CSS travel trailers equipped with certain SDS2 2-Burner Drop-in Cooktops because the internal aluminium burner tubes that connect to the gas valves may fracture and cause a gas leak - **fire risk**.

United States 06 February 2023: Nova Bus Inc. is recalling 17 units of 2022 LFS transit buses because during assembly, the power steering hose may not have been assembled correctly which can result in hose detachment and a loss of power steering assist - **crash risk**.

United States 06 February 2023: Tokai Rika Co LTD is recalling 106 units of front-seat outer right-side seat belt assemblies because the seat belt assembly force-limiter may not operate correctly, allowing the seat belt to extend further than intended after locking - **injury risk**.

United States 05 February 2023: Bombardier Recreational Products Inc. is recalling 1,720 units of 2022 Cam-Am Spyder F3 and F3-S motorcycles because the rear-view mirror lens may detach from the housing - **crash risk**.

United States 04 February 2023: Nexus RV's LLC is recalling 103 units of 2022 Triumph, Phantom, Viper, Ghost, Rebel, Wraith and Verrado motorhomes equipped with certain Electric Retractable Awnings because the welded seam on the fabric may separate, potentially allowing the

awning to drop beyond normal operation - **injury risk**.

Canada 03 February 2023: BMW is recalling 37 units of 2023 BMW 7-Series because a software problem may cause the front passenger seat position not to be recognized - **injury risk**.

Canada 03 February 2023: BMW is recalling 196 units of 2021-2023 BMW S1000R and 2020-2023 S1000XR motorcycles because the 'Dynamic Pro' riding mode settings were reset to the factory settings after a software update - **crash risk**.

United States 03 February 2023: Harbor Freight Tools is recalling 34,570 units of Holt Industries Deluxe Manual Fluid Extractor and Dispenser units because when the unit is in dispense mode, the pressure relief plug may fail and result in a build-up of excessive pressure - **injury risk**.

United States 03 February 2023: Winnebago Industries Inc. is recalling 9,720 units of 2020-2023 Solis, 2021-2023 Travato and 2022-2023 Ekko motorhomes equipped with certain Suburban Manufacturing Company SDS2 2-Burner Drop-in Cooktops because the internal aluminium burner tubes that connect to the gas valves may fracture and cause a gas leak - **fire risk**.

United States 03 February 2023: BMW of North America LLC is recalling 754 units of 2022-2023 S 1000R and 2020-2023 S 1000XR motorcycles because during a software update performed at a dealership, the "Dynamic Pro" riding mode feature "front wheel lift-off assistant" may have been inadvertently deactivated without alerting the rider - **crash risk**.

United States 03 February 2023: BMW of North America LLC is recalling 397 units of 2023 760i xDrive and i7 xDrive60 vehicles equipped with the Executive Lounge Seating Package because in certain seat monitoring conditions, the front passenger seat electronic control unit (ECU) software may not recognize the seat position and disable the front passenger air bag, knee air bag and active headrest - **injury risk**.

Canada 02 February 2023: Land Rover is recalling 439 units of 2023 Land Rover Defender, Discovery, Range Rover Sport and Range Rover Velar vehicles because an

North America

Recall Summary

oil channel in the engine camshaft carrier wasn't drilled correctly - [fire risk](#).

Canada 02 February 2023: Jaguar is recalling 10 units of 2023 Jaguar F-Pace vehicles because an oil channel in the engine camshaft carrier wasn't drilled correctly - [fire risk](#).

Canada 02 February 2023: Land Rover is recalling 19 units of 2023 Land Rover Range Rover vehicles because a convex mirror glass was incorrectly installed on the driver's door mirror - [crash risk](#).

United States 02 February 2023: Honda is recalling 114,686 units of 2018-2020 Fit and 2019-2022 HR-V vehicles because the rear-view camera image may not display when the engine is started with a key due to a design error in the audio display power circuit - [crash risk](#).

United States 02 February 2023: Jaguar Land Rover North America LLC is recalling 6,644 units of 2023 Range Rover, Range Rover Sport, Range Rover Velar, Discovery and Defender vehicles because the engine cam carrier oil channel may be blocked which can lead to an oil leak - [fire risk](#).

United States 02 February 2023: Jaguar Land Rover North America LLC is recalling 229 units of certain 2023 F-Pace vehicles because the engine cam carrier oil channel may be blocked which can lead to an oil leak - [fire risk](#).

United States 02 February 2023: Nissan North America Inc. is recalling 64,732 units of 2018-2023 LEAF vehicles because the Owner's Manual instructions for defroster operation are incorrect and may result in reduced defroster performance under specific conditions - [crash risk](#).

United States 02 February 2023: Toyota Motor Engineering & Manufacturing is recalling 16,679 units of 2021 RAV4 Prime Plug-In Hybrid vehicles because during certain cold weather driving conditions, while driving in EV Mode, the hybrid vehicle control engine control unit (HEV ECU) software may cause the hybrid system to shut down if the accelerator is rapidly pressed to further accelerate the vehicle, resulting in a stall - [crash risk](#).

Canada 01 February 2023: BMW is recalling 64 units of 2023 BMW 2-Series because on certain 2 Series Coupe



models, the rear seat backrest cover panels could crack when a side airbag deploys - [injury risk](#).

Canada 01 February 2023: Kia is recalling 1,359 units of 2023 Kia Telluride vehicles because the wiring for the side airbags in the second-row seat cushion assembly may be too long - [injury risk](#).

United States 01 February 2023: BMW of North America LLC is recalling 804 units of 2023 2 Series Coupe (230i, 230i xDrive, M240i, M240i xDrive) vehicles because the second-row seat backrest cover panels for the side air bags may break during deployment of the side air bags - [injury risk](#).

United States 01 February 2023: Volkswagen Group of America Inc. is recalling 20,904 units of 2021 ID.4 vehicles because software programming may cause the high voltage (HV) battery management control module to restart or the pulse inverter to deactivate - [crash risk](#).

United States 01 February 2023: Navico Group is recalling 4,746 units of RELiON InSight 48 V lithium-ion batteries because improperly formed capacitors may cause an internal battery leak and corrosion, resulting in a short circuit - [fire risk](#).

Contact

Get in touch for support from our global team of Auto Recall Specialists.



auto@securityexchange24.com



+44 (0)1491 683710



www.securityexchange24.com

Emergency

To access emergency support in the event of an incident, call our 24/7 crisis centre.

US: +1 305 384 4825

APAC: +61 2807 30186

UK & EU: +44 20 3284 8844

Training

Security Exchange provides a range of product contamination and recall, tamper and extortion mitigation and response consultancy services for the Contaminated Products Insurance market. In partnering with Salford University Business School, we deliver fully accredited, professional and bespoke industry-based training programmes in food and non-food, automotive, pharmaceutical, consumer goods and environmental management. For further information on these services, please contact us at enquiries@securityexchange24.com.