




SECURITY EXCHANGE



Security Exchange

Automotive Recall Summary: March 2023



North America

Recall Summary

Canada 31 March 2023: Demers is recalling 64 units of 2022-2023 Demers MX Series Ambulance and MXP Series Ambulance because the step under the rear doors may not have been properly welded which could cause it to fail when used - [injury risk](#).

Canada 31 March 2023: Rivian is recalling 9 units of 2022-2023 Rivian R1S vehicles because the backup lamps may not be visible from some viewing angles - [crash risk](#).

Canada 31 March 2023: Gulf Stream Coach is recalling 55 units of 2023-2024 Gulf Stream BT Cruiser and Gulf Stream Conquest motorhomes because a problem with the latch for the entry door could cause it to fail - [injury risk](#).

Canada 31 March 2023: Altec Industries is recalling 2 units of 2015-2023 Altec DM47 digger derricks with a dual pole rack system because a weld could be missing on the rear pole rack - [injury risk](#).

Canada 31 March 2023: Forest River is recalling 6 units of 2023 East to West Della Terra RV trailers because they were equipped with safety chains that are not strong enough - [crash risk](#).

United States 31 March 2023: Tesla Inc. is recalling 422 units of 2018-2019 Model 3 vehicles because the front suspension lateral link fasteners may loosen, allowing the lateral link to separate from the sub-frame - [crash risk](#).

United States 31 March 2023: Kia America Inc. is recalling 51,568 units of 2022 and 2023 Carnival vehicles because the auto-reverse feature for the power sliding doors (PSD) may not activate in all situations - [injury risk](#).

United States 31 March 2023: Rivian Automotive LLC is recalling 5,030 units of 2022-2023 R1S vehicles because the reverse light beam may not be visible from certain angles - [crash risk](#).

United States 31 March 2023: Forest River Inc. is recalling 98 units of 2023 East to West Della Terra and Silver Lake travel trailers because the drawbar assembly containing the A-frame and safety chains may be insufficient for the Gross Vehicle Weight Rating (GVWR) and could potentially break - [crash risk](#).

United States 31 March 2023: Forest River Inc. is recalling



70 units of 2023 Cherokee CKT36FBOP Travel Trailers because the safety chains may be insufficient for the Gross Vehicle Weight Rating (GVWR) listed on the federal placard which can allow the trailer to detach - [crash risk](#).

United States 31 March 2023: Gulf Stream Coach Inc. is recalling 557 units of 2023-2024 Conquest and BT Cruiser Class C Mini Motor Homes because the entry door latch may fail and not allow entry or exit - [injury risk](#).

United States 31 March 2023: Mercedes-Benz USA LLC is recalling 3 units of 2023 AMG CLA 45 vehicles because the tires may leak air - [crash risk](#).

United States 31 March 2023: Great Dane Trailers is recalling 562 units of 2023 Champion Dry Van trailers because the wheel hubs may have an insufficient amount of lubrication which could cause the hub bearings to fail - [crash risk](#).

United States 31 March 2023: Lippert is recalling 2,399 units of Way Solar Panels because the solar panel mounting hardware may become loose and pull through the slot in the panel - [crash risk](#).

United States 31 March 2023: Felling Trailers Inc. is recalling 6 units of 2022-2023 Felling Trailers Drop-Deck and 2023 Deck-Over trailers, equipped with a Warn Winch and a wireless handheld remote because water may enter the handheld remote control for the winch and cause circuit board corrosion which can allow the winch to operate unintentionally - [injury risk](#).

United States 31 March 2023: Winnebago Industries Inc. is recalling 1,180 units of 2021-2023 Ekko motorhomes because the 12-Volt charging system may have improperly routed wires and loose electrical connections which can overload the electrical circuits and cause damage to electrical components, including the auxiliary alternator - [fire risk](#).

Canada 30 March 2023: Jayco is recalling 57 units of 2022-2023 Entegra Coach Anthem, Aspire, Cornerstone, Reatta, Reatta XL and Jayco Embark motorhomes because a software problem in the vehicle control module could cause a sudden loss of power - [crash risk](#).

North America

Recall Summary

Canada 30 March 2023: Honda is recalling 79 units of 2023 Honda Civic Type-R models because the driver's seat frame may not have been properly welded - **injury risk**.

Canada 30 March 2023: Spartan Fire is recalling 4 units of 2022-2023 Spartan Gladiator and Spartan Metro Star fire trucks because the retaining clips (keepers) may not have been installed correctly on the steer axle nuts - **crash risk**.

Canada 30 March 2023: Navistar is recalling 24 units of 2022 International HV, 2022-2024 International LT and International RH trucks because a problem with the engine control software could cause the throttle pedal not to work - **crash risk**.

United States 30 March 2023: Honda is recalling 563,711 units of 2007-2011 CR-V vehicles because an accumulation of road salt may cause the frame to corrode and possibly detach the rear trailing arm - **crash risk**.

United States 30 March 2023: Honda is recalling 640 units of 2023 Civic Type R vehicles because the driver's seat frame may not have been welded properly which can cause the seat cushion frame to break - **injury risk**.

United States 30 March 2023: Jayco Inc. is recalling 19 units of 2021-2022 Jayco Atlante, Precept, Precept Prestige, Entegra Emblem, Vision and Vision XL motorhomes because the rear stabilizer bar attachment brackets may break and separate from the vehicle - **crash risk**.

United States 30 March 2023: Four Degree Trailer Company is recalling 65 units of 2019-2022 Lo-LAL and IPT-EOT trailers, equipped with a Warn Winch and a wireless handheld remote, because water may enter the handheld remote control for the winch and cause circuit board corrosion which can allow the winch to operate unintentionally - **injury risk**.

United States 30 March 2023: Navistar Inc. is recalling 770 units of 2021-2024 International LT and RH trucks because the engine control module (ECM) may be unresponsive to throttle pedal application which can cause the vehicle to unexpectedly slow to idle speed on the road - **crash risk**.

United States 30 March 2023: Jayco Inc. is recalling 2 units



of 2022 Entegra Coach Qwest motorhomes because the wiring harnesses for the swivel-seats may have been incorrectly installed and may become damaged which can cause the front side air bags not to deploy as intended - **injury risk**.

United States 30 March 2023: Jaguar Land Rover North America LLC is recalling one 2023 Land Rover Range Rover vehicle because a gasket on the turbo oil drainpipe may be incorrectly installed or missing which can result in an oil leak - **fire risk**.

United States 30 March 2023: Jaguar Land Rover North America LLC is recalling 2,881 units of 2019-2021 Land Rover Range Rover PHEV and 2019-2022 Land Rover Range Rover Sport PHEV vehicles because the water pump pulley drive belt may become damaged or detach which can allow the engine to overheat - **fire risk**.

United States 30 March 2023: Altec Industries Inc. is recalling 631 units of 2016-2022 DM, DH, DC, DL, D2000, D3000, D4000 series digger derricks and AM55 aerial devices because the base of the rear pole rack may be missing a weld - **injury risk**.

United States 30 March 2023: Jayco Inc. is recalling 972 units of 2022-2024 Jayco Embark, Entegra Anthem, Aspire, Cornerstone, Reatta and Reatta XL motorhomes because a vehicle control module software error may cause loss of drive power or loss of key safety functions, such as loss of head lights or windshield wipers - **crash risk**.

United States 30 March 2023: Capacity of Texas is recalling 53 units of 2020-2023 TJ5000 vehicles because the front-drive steer axle fasteners may loosen, resulting in a complete separation of the axle assembly joints - **crash risk**.

Canada 29 March 2023: Volkswagen is recalling 1,455 units of 2023 Volkswagen ID.4 vehicles because water could leak into the door handle(s) - **injury risk**.

Canada 29 March 2023: Kia is recalling 5,823 units of 2022-2023 Kia Carnival minivans because the power sliding door may not stop and reverse if it is blocked - **injury risk**.

Canada 29 March 2023: Ferrari is recalling one 2021-2023

North America

Recall Summary

Ferrari SF90 vehicle because the passenger side airbag could impact a child seat if installed in the passenger seat - [injury risk](#).

United States 29 March 2023: BMW of North America LLC is recalling 51 units of 2019-2021 330i, 330i xDrive, M340i xDrive, 2020-2021 X3 sDrive30i, X3 xDrive30i, X3 M40i, X3M, 2021 X3 xDrive30e, X4 xDrive30i and X4M vehicles because the seat frame may not have been welded properly to the seat rails - [injury risk](#).

United States 29 March 2023: Kia America Inc. is recalling 2,689 units of 2015-2019 Soul EV vehicles equipped with an E400 battery because the high-voltage battery pack may experience an electrical short-circuit while driving - [fire risk](#).

United States 29 March 2023: Volkswagen Group of America Inc. is recalling 19 units of 2020 Q7 vehicles because incompatibility between the front camera control software and the heating element used for the front camera on the windshield may cause the heating element to overheat - [fire risk](#).

United States 29 March 2023: Volkswagen Group of America Inc. is recalling 16,207 units of 2023 ID4 vehicles because the affected vehicles may have been manufactured with door handles that allow water to enter the circuit board assembly which can cause the door to open unexpectedly when the vehicle is subject to high lateral forces at speeds below 9 mph/15 kmh - [injury risk](#).

United States 29 March 2023: Volkswagen Group of America Inc. is recalling 15,874 units of 2022 TAOS vehicles because the fuel delivery pump may break which could cause a sudden engine stall - [crash risk](#).

United States 29 March 2023: Volkswagen Group of America Inc. is recalling 143,053 units of 2018-2021 Atlas and 2020 Atlas Cross Sport vehicles because the passenger occupant detection system (PODS) may experience a fault in the wiring and deactivate the front passenger air bag when the seat is occupied - [injury risk](#).

Canada 28 March 2023: Morgan Olson is recalling 111 units of 2022-2023 Morgan Olson C250 vehicles because a wire for the ignition button could be damaged by contact with a steel support bracket - [crash risk](#).



Canada 28 March 2023: Genesis is recalling 39 units of 2023 Genesis G90 vehicles because there may be a problem with the seat belt pretensioners - [injury risk](#).

Canada 28 March 2023: Daimler Truck North America is recalling one 2023 Thomas Built Saf-T-Liner C2 School Bus because the automatic low voltage disconnect switch could fail in the open position - [injury/crash risk](#).

United States 28 March 2023: Hyundai Motor America is recalling 575 units of 2023 Genesis G90 vehicles because in the event of a crash, the front driver-side, passenger-side and rear seat belt pretensioners may explode upon deployment - [injury risk](#).

United States 28 March 2023: Daimler Trucks North America LLC is recalling 24,282 units of 2020-2021 Freightliner Cascadia vehicles because the hazard warning lights may flash improperly during an Advanced Braking Assist event - [crash risk](#).

United States 28 March 2023: Daimler Trucks North America LLC is recalling 380 units of 2021-2023 Thomas Built Bus SAF-TLINER C2 JOULEY school buses, equipped with an automatic low voltage disconnect switch, because the automatic low voltage disconnect switch may fail, resulting in a loss of drive power, power steering, or vehicle lighting - [crash risk](#).

Canada 27 March 2023: Vermeer is recalling 332 units of 2016-2023 Vermeer BC700XL brush chipper trailers because the bolts that attach the safety chains aren't long enough - [crash risk](#).

Canada 27 March 2023: Ford is recalling 3 units of 2023 Ford Edge and 2023 Lincoln Nautilus vehicles because the upper tether anchorage for a child car seat may not be properly welded to the second row left seat frame - [injury risk](#).

United States 27 March 2023: Cummins Inc. is recalling 445 units of PowerDrive 7000 electric drive systems because the System Control Module (SCM) may activate the anti-rollback feature causing the vehicle to reverse faster than expected - [crash risk](#).

United States 27 March 2023: Vermeer Manufacturing

North America

Recall Summary

Company is recalling 3,317 units of 2016-2023 BC700XL brush chipper trailers. The incorrect retention bolt may have been installed in the safety chain assembly - **injury/crash risk**.

United States 27 March 2023: Lightning eMotors Inc. is recalling 148 units of 2020 FE4-86 and FT3-43, 2019-2021 FE4-129 and 2019-2022 FT3-86 vehicles because the battery packs may have defective structural welds and experience an internal radiator leak causing battery failure - **fire risk**.

Canada 24 March 2023: Jayco is recalling 4 units of 2023 Jayco North Point Fifth Wheel Trailer RV trailers because the U-bolts that attach the axles to the suspension may not be properly tightened - **crash risk**.

Canada 24 March 2023: Grand Design RV is recalling 1,061 units of 2023 Grand Design Imagine, Momentum Fifth Wheel, Momentum Travel Trailer, Reflection Fifth Wheel, Reflection Travel Trailer, Solitude Fifth Wheel and Transcend RV trailers because the tire and loading information label may not have been installed - **crash risk**.

Canada 24 March 2023: Airstream is recalling 325 units of 2021-2023 Airstream Atlas, Bambi, Base Camp and Interstate RV trailers and motorhomes because the aluminium tubes that connect the gas valves to the cooktop burners could crack - **fire risk**.

United States 24 March 2023: Forest River Inc. is recalling 19 units of 2023 Pause travel trailers because the brake wire was routed incorrectly through the suspension which may result in a pinched wire - **crash risk**.

United States 24 March 2023: Tesla Inc. is recalling 35 units of 2023 Semi trucks because the electronic parking brake valve module (PVM) may fail to move into the park position when the parking brake is activated - **crash risk**.

United States 24 March 2023: Daimler Vans USA LLC is recalling 6,857 units of 2019-2022 Mercedes-Benz Sprinter and Freightliner Sprinter vehicles because the instrument cluster may fail to display any information when the vehicle is started - **crash risk**.

United States 24 March 2023: Mercedes-Benz USA LLC is



recalling 6 units of 2021 Maybach S580 and S580 vehicles because the bulkhead that separates the engine compartment from the passenger compartment may not have been properly sealed, causing water to drain into the passenger compartment - **injury risk**.

United States 24 March 2023: Forest River Inc. is recalling 12 units of 2023 Forest River Pause Travel trailers because the breakaway switch may be incorrectly wired and cause the battery to not charge, resulting in no power to the breakaway switch - **crash risk**.

United States 24 March 2023: Daimler Vans USA LLC is recalling 6,857 units of 2019-2022 Mercedes-Benz Sprinter and Freightliner Sprinter vehicles because the instrument cluster may fail to display any information when the vehicle is started - **crash risk**.

United States 24 March 2023: Jayco Inc. is recalling 37 units of 2023 Northpoint FW travel trailers because the axle U-bolts may not be tightened properly which can cause the axle to move out of position - **crash risk**.

United States 24 March 2023: Shadow Trailer LLC is recalling 270 units of 2016-2023 Living Quarter trailers, equipped with certain SDS2 2-Burner Drop-in Cooktops, because the internal aluminium burner tubes that connect to the gas valves may fracture and cause a gas leak - **fire risk**.

United States 24 March 2023: Ford Motor Company is recalling 19 units of 2023 Edge and Lincoln Nautilus vehicles because the child seat tether wire welds on the second row left-side seat back frame may be insufficient which can reduce the seat's ability to properly restrain a child during a crash - **injury risk**.

United States 23 March 2023: Chrysler FCA US LLC is recalling 165 units of Mopar frame assemblies because when installed in a vehicle, a stud on the frame assembly may puncture the fuel tank during a crash and result in a fuel leak - **fire risk**.

United States 23 March 2023: Chrysler FCA US LLC is recalling 35,829 units of 2020-2022 Jeep Wrangler vehicles because a stud on the frame assembly may puncture the fuel tank in a crash which can result in a fuel

North America



Recall Summary

leak - **fire risk**.

United States 23 March 2023: Honda is recalling 15,848 units of 2022 Honda NVA110B motorcycles because the speedometer cable was incorrectly routed and may break or detach - **crash risk**.

United States 23 March 2023: Spartan Fire LLC is recalling 12 units of 2020, 2022 and 2023 Gladiator and 2023 MetroStar vehicles because the front-drive steer axle fasteners may loosen, resulting in a complete separation of the axle assembly joints - **crash risk**.

United States 23 March 2023: 9299-5000 Québec Inc. is recalling 61 units of 2020-2023 HÉLIO O2 travel trailers, equipped with certain SDS2 2-Burner Drop-in Cooktops because the internal aluminium burner tubes that connect to the gas valves may fracture and cause a gas leak - **fire risk**.

United States 23 March 2023: Capri Campers LLC is recalling 6 units of 2022 Capri Camper Retreat truck bed campers, equipped with certain SDS2 2-Burner Drop-in Cooktops because the internal aluminium burner tubes that connect to the gas valves may fracture and cause a gas leak - **fire risk**.

United States 23 March 2023: Autocar LLC is recalling 909 units of 2022-2023 ACX Xpeditor and 2020-2023 DC Legend vehicles because the powertrain driveline centre support bearing hardware may not have been properly secured - **crash risk**.

United States 23 March 2023: Autocar LLC is recalling 55 units of 2020-2022 ACX Xpeditor vehicles because the external fuse box may short circuit due to water intrusion - **crash risk**.

Canada 22 March 2023: Nova Bus is recalling 5 units of 2023 Nova Bus LFS buses because defective bolts were used to attach the radius rods to the drive axle - **crash risk**.

Canada 22 March 2023: Audi is recalling 1,103 units of 2022-2023 Audi Q4 E-Tron vehicles because the head curtain airbags could contact the metal part of the front door seals when they inflate in a crash - **injury risk**.

Canada 22 March 2023: Volvo is recalling 5 units of 2023 Volvo S60, XC60 and XC90 vehicles because a software problem could cause an “e-Call service required” message to falsely display when there is no issue with the emergency calling (e-Call) system - **injury risk**.

United States 22 March 2023: Volkswagen Group of America Inc. is recalling 5,224 units of 2022-2023 Q4 E-Tron SUV and Q4 E-Tron Sportback vehicles because during deployment, the head curtain air bag could deform the door seal and expose the metal inlay within the seal which could tear the air bag - **injury risk**.

United States 22 March 2023: Alexis Fire Equipment Company is recalling 3 units of 2022 Emergency Utility, Flatbed Brush and 300 Gallon Mini Pumper Fire Apparatus vehicles, equipped with a Warn Winch and a wireless handheld remote, because water may enter the handheld remote control for the winch and cause circuit board corrosion which can allow the winch to operate unintentionally - **injury risk**.

United States 22 March 2023: Volvo Car USA LLC is recalling 329 units of 2023 S60, V60CC, XC60, XC90, XC40 and C40 vehicles because a diagnostic trouble code (DTC) may be falsely detected for the emergency call system (e-call) and display “e-Call Service Required” in the driver information module (DIM) - **injury risk**.

Canada 21 March 2023: Hélio is recalling 114 units of 2020-2023 Hélio O Series RV trailers because the aluminium tubes that connect the gas valves to the cooktop burners could crack - **fire risk**.

Canada 21 March 2023: Ducati is recalling 12 units of 2023 Ducati Desert X motorcycles equipped with Ducati Performance accessory soft side bags because the instructions for how to install the right-side soft bag may be unclear - **fire risk**.

Canada 21 March 2023: Infiniti is recalling 27 units of 2022 Infiniti QX50 and 2023 Infiniti QX55 vehicles because the wrong door latch may have been installed in the front passenger door - **injury risk**.

Canada 21 March 2023: REV Group is recalling 25 units of 2023 Fleetwood RV Discovery LXE, Flair, Frontier and

North America

Recall Summary

2023 Holiday Rambler Armada, Eclipse, Invicta, Nautica and Vacationer motorhomes because a problem with the latch for the entry door could cause it to fail - [injury risk](#).

Canada 20 March 2023: Winnebago is recalling 335 units of Winnebago 2022-2023 Ekko, 2020-2023 Solis and 2021-2023 Travato motorhomes because the aluminium tubes that connect the gas valves to the cooktop burners could crack - [fire risk](#).

Canada 20 March 2023: Prevost is recalling 5 units of 2023 Prevost H3-45 Coach and H3-45 VIP buses because when the hazard lights are switched on with the ignition switch in the "OFF" position, the signal lamps may not flash at the same time - [crash risk](#).

Canada 20 March 2023: Prevost is recalling 4 units of 2023 Prevost H3-45 Coach buses because the emergency exit window latches may be difficult to open - [injury risk](#).

United States 20 March 2023: Prevost Car Inc. is recalling one 2023 H3-45 vehicle because the emergency exit window may require excessive force to open - [injury risk](#).

United States 20 March 2023: Prevost Car Inc. is recalling 26 units of 2022-2023 H3-45 VIP and 2023 H3-45 vehicles because when activating the hazard warning lights, the turn signal lights may not flash simultaneously if the ignition is off - [crash risk](#).

United States 20 March 2023: Kentucky Trailer Manufacturing is recalling 5 units of 2021-2022 Kentucky Trailer XL-12 trailers, equipped with certain Warn Winches with a wireless handheld remote, because water may enter the handheld remote control for the winch and cause circuit board corrosion which can allow the winch to operate unintentionally - [injury risk](#).

United States 20 March 2023: PACCAR Incorporated is recalling 25 units of 2023-2024 Peterbilt 579 trucks because the Intellipark Tractor Park Valve Module (PVM) may intermittently become stuck in the un-parked position and fail to move into the park position when the park switch is activated - [crash risk](#).

United States 20 March 2023: Forest River Inc. is recalling 20 units of 2019-2023 Continental Cargo, 2019-2022



Cargo Mate and 2020 Cross Bow cargo trailers, equipped with certain Warn Winches with a wireless handheld remote, because water may enter the handheld remote control for the winch and cause circuit board corrosion which can allow the winch to operate unintentionally - [injury risk](#).

United States 20 March 2023: Nissan North America Inc. is recalling 48 units of 2023 Infiniti QX55 and 2022 Infiniti QX50 vehicles because the incorrect door latch may have been installed in the front right-side passenger door lock assembly, preventing the front right-side door lock from automatically locking - [injury risk](#).

United States 20 March 2023: Meritor Inc. is recalling 37 units of front drive steer axles because the front-drive steer axle fasteners may not have been tightened sufficiently and could come loose, resulting in a complete separation of the axle assembly joints - [crash risk](#).

Canada 17 March 2023: Mercedes-Benz is recalling 6,870 units of 2022-2023 Mercedes-Benz GLE Class and GLS Class vehicles because the window trim on the rear doors may not be properly attached - [crash risk](#).

Canada 17 March 2023: Kia is recalling 853 units of 2022-2023 Kia Carnival vehicles because they were equipped with a 4-pin accessory trailer wiring harness kit that could fail - [fire risk](#).

Canada 17 March 2023: Hyundai is recalling 24,676 units of 2020-2023 Hyundai Palisade vehicles because the windshield wiper motor may stop working when snow and/or ice builds up on the windshield - [crash risk](#).

Canada 17 March 2023: Hyundai is recalling 1,897 units of Hyundai 2022-2023 Santa Cruz and 2019-2023 Sante Fe vehicles because they were equipped with a 4-pin accessory trailer wiring harness kit that could fail - [fire risk](#).

United States 17 March 2023: Mercedes-Benz USA LLC is recalling 70,225 units of 2022-2023 GLE350, GLE450, GLE580, GLS450, GLS580, Maybach GLS600, AMG GLE53, AMG GLE63 S and AMG GLS63 vehicles because the rear door window trim bars may detach from the vehicle while driving - [crash/injury risk](#).

North America

Recall Summary

United States 17 March 2023: Mercedes-Benz USA LLC is recalling 61,450 units of 2020-2021 GLE350, GLE450, GLS450, GLS580, 2021 AMG GLE53, AMG GLE63, Maybach GLS600, AMG GLS63 and 2020 GLE580 vehicles because the air conditioner drain hoses may have been incorrectly installed, causing water to drain into the passenger compartment - [crash/injury risk](#).

United States 17 March 2023: Hyundai Motor America is recalling 567,912 units of 2019-2023 Santa Fe, 2021-2023 Santa Fe HEV, 2022-2023 Santa Fe Plug-in HEV and Santa Cruz vehicles potentially equipped with a tow hitch harness installed as original equipment or purchased as an accessory through a Hyundai dealership, because water accumulation on the tow hitch harness module printed circuit board (PCB) may cause an electrical short which can result in a fire - [injury risk](#).

United States 17 March 2023: Hyundai Motor America is recalling 167,085 units of 2021-2023 Palisade vehicles because the windshield wiper motor may operate intermittently or fail to operate due to snow or ice build-up on the windshield, causing the wipers to fail - [crash risk](#).

United States 17 March 2023: Kia America Inc. is recalling 3,555 units of 2022-2023 Carnival vehicles equipped with a tow hitch harness installed as original equipment or purchased as an accessory through a Kia dealership, because water accumulation on the tow hitch harness module printed circuit board (PCB) may cause an electrical short which can result in a fire - [injury risk](#).

United States 17 March 2023: Porsche Cars North America Inc. is recalling 130 units of 2020 Taycan Turbo, 2021 Taycan, Taycan 4S Cross Turismo, 2022 Taycan, Taycan Turbo, Taycan GTS, Taycan 4 Cross Turismo, Taycan 4S Cross Turismo, 2020-2022 Taycan 4S and Taycan Turbo S, and 2023 Taycan vehicles because when there is an unbelted passenger, the seat belt warning light and audible chime will not activate as intended - [injury risk](#).

United States 17 March 2023: Bombardier Recreational Products Inc. is recalling 34,457 units of 2020-2023 Spyder RT and 2022-2023 Ryker motorcycles because the brake lights may stay illuminated even if the brake pedal is not pressed - [crash risk](#).



Canada 16 March 2023: Textron is recalling 4,600 units of 2020-2023 Arctic Cat M 8000 snowmobiles because the snap ring that attaches the fuel dampener to the fuel rail could come loose and fall out - [fire risk](#).

Canada 16 March 2023: Rainbow Trailers is recalling 38 units of 2017-2023 Rainbow Trailers Aluminum Cargo Trailer single-axle cargo trailers because the hitch frame may fail where it's welded to the cargo box - [crash risk](#).

Canada 16 March 2023: General Motors is recalling 642 units of 2023 Cadillac XT5, XT6, Chevrolet Blazer, Traverse and GMC Acadia vehicles because a problem inside the transmission could cause the left-front axle shaft to separate from the transmission - [crash/injury risk](#).

Canada 16 March 2023: Navistar is recalling 2 units of 2023 International HX and Lonestar trucks because when the parking switch is pulled on the dashboard, the park valve module may stick in the un-parked position - [crash risk](#).

Canada 16 March 2023: Navistar is recalling 2,249 units of 2020-2024 International HX trucks because the mounting brackets for the front grille surround (trim) could loosen or detach - [crash risk](#).

Canada 16 March 2023: Keystone is recalling 21 units of 2022-2023 Keystone Cougar RV trailers because an emergency exit window may not have been installed - [injury risk](#).

Canada 16 March 2023: Bombardier Recreational Products is recalling 8,414 units of 2022-2023 Can-Am Ryker and 2020-2023 Can-AM Spyder RT vehicles because a problem with the brake light switch could cause the brake lamps to stay on after you release the brakes - [crash risk](#).

United States 16 March 2023: Ducati North America is recalling 65 units of Ducati Performance Desert X Soft Side Bags Kits, designed to fit 2023 DesertX motorcycles, because the right-side bag may contact the exhaust during motorcycle use - [injury/fire/crash risk](#).

United States 16 March 2023: Volvo Trucks North America is recalling 726 units of 2024 VNR, VNL and VHD vehicles because the hub covers do not properly fit on the hub and

North America

Recall Summary

can detach from the vehicle - [crash risk](#).

United States 16 March 2023: Honda is recalling 330,318 units of 2020-2021 Pilot and Ridgeline and 2020-2022 Passport and Odyssey vehicles because the heating pads behind both side-view mirrors may not be bonded properly, allowing the mirror glass to detach - [crash risk](#).

United States 16 March 2023: Navistar Inc. is recalling 5,769 units of 2020-2024 International HX vehicles because the grille surround may corrode and detach from the truck - [crash risk](#).

United States 16 March 2023: Navistar Inc. is recalling 24 units of 2023 International HV, HX, LT, RH and Lonestar vehicles because the Intellipark Tractor Park Valve Module (PVM) may intermittently become stuck in the un-parked position and fail to move into the park position when the park switch is activated - [crash risk](#).

United States 16 March 2023: Keystone RV Company is recalling 276 units of 2022-2023 Cougar travel trailers because these vehicles may have been manufactured without an emergency exit window - [injury risk](#).

United States 16 March 2023: General Motors LLC is recalling 8,744 units of 2023 Cadillac XT6, GMC Acadia, Chevrolet Blazer, Traverse and 2022-2023 Cadillac XT5 vehicles because the transmission may have been built with an incorrect sun gear which can result in the driver-side half-shaft disengaging from the transmission - [crash risk](#).

United States 15 March 2023: Alliance RV LLC is recalling 57 units of 2023 Valor 21T15 travel trailers because the incorrect size wheel and tire assemblies were installed and may become overloaded - [crash risk](#).

United States 15 March 2023: Ford Motor Company is recalling 18 units of 2023 F-150 Lightning pickup trucks because the high-voltage battery pack may experience an electrical short-circuit when the battery is fully charged or near fully charged - [fire risk](#).

Canada 14 March 2023: Ford is recalling 3 units of 2023 Ford Bronco with the Wildtrak trim package because there may be an internal problem with the steering gear - [crash risk](#).



United States 14 March 2023: REV Recreation Group is recalling 479 units of 2023 Fleetwood Bounder, Flair, Flex, Fortis, Southwind, Discovery, Discovery LX, Frontier, Frontier GTX, Pace Arrow, Holiday Rambler Admiral, Eclipse, Invicta, Vacationer, Armada, Endeavor, Navigator, Nautica and American Coach American Tradition motorhomes because the entry door latch may fail and not allow entry or exit - [injury risk](#).

United States 14 March 2023: Dorel Juvenile Group is recalling 14,510 units of Maxi-Cosi Coral XP Rear-facing Infant Seats because the child seat inner carrier is not sufficient to restrain a child without the use of the outer carrier - [injury risk](#).

Canada 13 March 2023: Ford is recalling 465 units of 2023 Ford Maverick trucks equipped with the trailer tow package because a wiring circuit to the trailer tow electrical connector is missing - [crash risk](#).

United States 10 March 2023: Kibbi LLC is recalling 63 units of 2022-2023 Renegade RV Classic, Explorer and XL Motorhomes because the entry door latch may fail and not allow entry or exit - [injury risk](#).

United States 10 March 2023: Ford Motor Company is recalling 1,280,726 units of 2013-2018 Fusion and Lincoln MKZ vehicles because the front brake hoses may rupture and leak brake fluid - [crash risk](#).

United States 10 March 2023: Ford Motor Company is recalling 222,454 units of 2021 F-150 vehicles because the windshield wiper arms may break, causing the windshield wipers to fail - [crash risk](#).

United States 10 March 2023: Ford Motor Company is recalling 1,651 units of 2021-2022 Bronco vehicles equipped with 8-inch SYNC infotainment screens that were previously remedied under a previous recall because the rear-view camera image may still be displayed after a backing event has ended - [crash risk](#).

United States 10 March 2023: Ford Motor Company is recalling 644 units of 2022 F-53 and F-59 vehicles because the rear brake calliper attachment bolts may not be tightened correctly which can allow the calliper to loosen and possibly damage the wheel or brake lines - [crash risk](#).

North America



Recall Summary

United States 10 March 2023: Ford Motor Company is recalling 2,716 units of 2023 Maverick vehicles because a missing electrical circuit may cause the trailer taillights to not illuminate as intended when utilizing the vehicle trailer tow electrical connector - [crash risk](#).

Canada 09 March 2023: Spartan Fire is recalling 18 units of 2022-2023 Spartan FC-94, Gladiator and Metro Star fire trucks because the transmission control module (TCM) may not be programmed correctly - [fire risk](#).

United States 09 March 2023: Rivian Automotive LLC is recalling 30 units of 2022-2023 R1S vehicles because the fasteners that secure the right and left side curtain air bags may be improperly secured - [injury risk](#).

United States 09 March 2023: Gilbarco Inc. is recalling 10,000 units of Orpak/Gasboy automatic tank gauge and environmental monitoring systems because the capacitor may crack, causing overheating - [fire risk](#).

United States 09 March 2023: Chrysler FCA US LLC is recalling 330 units of Mopar Hydraulic Control Unit/Anti-lock Brake system modules (HCU) because when installed in a vehicle, the HCU Module may falsely read pressure in the primary circuit and illuminate the brake lights, as well as allow the vehicle to start and shift out of park without first applying the brake pedal - [crash risk](#).

United States 09 March 2023: Honda is recalling 448,613 units of 2017-2020 CR-V, 2018-2019 Accord and Accord Hybrid, 2018-2020 Odyssey, 2019 Insight and 2019-2020 Acura RDX vehicles because a manufacturing issue with the front seat belts may cause the seat belt buckle channel to interfere with the release button, preventing the seat belt buckle from latching - [injury risk](#).

Canada 08 March 2023: Kia is recalling 2,593 units of 2021-2023 Kia K5 vehicles because the side curtain airbag(s) may not have been installed correctly - [injury risk](#).

Canada 08 March 2023: Navistar is recalling 4 units of 2023-2024 International MV trucks because the bolts for the battery box could be missing or may not have been tightened properly - [crash risk](#).

Canada 08 March 2023: Navistar is recalling 2 units of

2023-2024 International MV trucks because the spring wedge shims for the rear axle may have been installed backwards - [crash risk](#).

Canada 08 March 2023: Grand Design RV is recalling 21 units of 2023 Grand Design Imagine Aim RV trailers because the compliance label and tire and loading information label lists incorrect tire information - [crash risk](#).

United States 08 March 2023: Ford Motor Company is recalling 343 units of 2023 Bronco Wildtrak and 2022 Bronco Raptor vehicles because internal damage to the steering gear may require increased steering effort or cause the steering wheel to lock-up - [crash risk](#).

United States 08 March 2023: Spartan Fire LLC is recalling 166 units of 2022-2024 Gladiator, Metro Star, FC-94 and KME Panther fire trucks because after the vehicle is reversed, the transmission control module (TCM) may fail to achieve the 4th gear lockup needed to initiate the water pump - [injury risk](#).

United States 08 March 2023: Eveland's Inc. is recalling 25 units of 2022 Scamp Trailer 13ft travel trailers, equipped with certain 2-burner Cooktops, because the burner control valves may become damaged causing a gas leak - [fire risk](#).

United States 08 March 2023: Navistar Inc. is recalling 660 units of 2023 International HV and 2023-2024 International MV vehicles because the rear axle spring wedge shim may have been incorrectly installed which can cause U-joint failure and result in driveshaft separation - [crash risk](#).

United States 08 March 2023: Navistar Inc. is recalling 791 units of 2023 International HV and 2023-2024 International MV vehicles because the assembly bolts used to attach the battery box to the mounting bracket may be loose or missing - [crash risk](#).

United States 08 March 2023: Terex Advance Mixer Inc. is recalling certain 2022-2023 Front Discharge Mixer Commander and Charger vehicles because improper installation or tightening of the steering shaft may cause it to come loose from the steering column and result in a loss of steering control - [crash risk](#).

North America

Recall Summary

Canada 07 March 2023: New Flyer is recalling 297 units of 2011-2017 New Flyer XD40, 2013 New Flyer XD60 and 2019-2023 New Flyer XDE60 transit buses because the emergency exit windows could open suddenly in a crash - **injury risk**.

United States 07 March 2023: Kia America Inc. is recalling 188,912 units of 2021-2023 K5 vehicles because the side curtain air bags may have been installed incorrectly, causing them not to deploy properly in the event of a crash - **injury risk**.

United States 07 March 2023: Terex Advance Mixer Inc. is recalling 20 units of 2022 Front Discharge Mixer Commander vehicles because front-drive steer axle fasteners may not have been tightened sufficiently and could come loose, resulting in a complete separation of the axle assembly joints - **crash risk**.

United States 07 March 2023: Bentley Motors Inc. is recalling 1,610 units of 2020-2021 Continental GTC vehicles because due to a sharp edge on the air bag deflector bracket, the seat air bags may tear during deployment - **injury risk**.

United States 07 March 2023: AROW Global Corp. is recalling 1,500 units of MV204 and MV207 emergency exit windows because during a crash, the emergency exit window latch may fail and allow the window to open - **injury risk**.

United States 07 March 2023: SAF-Holland is recalling 349 units of ADZ-123-9 Truck Suspensions because the rear suspension lower control arm may fail - **crash risk**.

United States 07 March 2023: Grand Design RV LLC is recalling 139 units of 2023 Imagine AIM travel trailers because the Federal Certification Label incorrectly states the tire size and inflation pressure requirement - **crash risk**.

Canada 06 March 2023: Hino is recalling 21 units of 2023 Hino L7 trucks because the wrong brake rotors may have been installed on the front wheel hubs - **crash risk**.

Canada 06 March 2023: Triumph is recalling 121 units of 2023 Triumph Bonneville T120 motorcycles because the left-front brake disc could loosen and detach from the

wheel assembly - **crash risk**.

United States 06 March 2023: Newell Coach Corp. is recalling 28 units of 2023-2024 P50 motor coaches because the brake lights may fail to illuminate unless the brake pedal is fully depressed - **crash risk**.

United States 06 March 2023: Triumph Motorcycles America Ltd is recalling 988 units of 2023 Bonneville T120 and Bonneville T120 Black motorcycles because the left-hand side (LHS) brake disc may be improperly secured and can detach - **crash risk**.

Canada 03 March 2023: Toyota is recalling 13,556 units of 2022-2023 Toyota Tundra trucks because the bedcover could come loose while driving and detach from the truck - **injury risk**.

Canada 03 March 2023: Forest River is recalling 21 units of 2020-2023 Palomino Solaire RV trailers because the supports for the fresh-water tank may not have been installed - **crash risk**.

United States 03 March 2023: Mack Trucks Inc. is recalling 17 units of 2023 Granite (GR) vehicles because the front-drive steer axle fasteners may not have been tightened sufficiently and could come loose, resulting in a complete separation of the axle assembly joints - **crash risk**.

United States 03 March 2023: Harbor Freight Tools is recalling 41,715 units of Central Hydraulics High Position Motorcycle Lifts because the lift welds or tubing may break which can allow the lift to fall or drop the motorcycle - **injury risk**.

United States 03 March 2023: Forest River Inc. is recalling 272 units of 2020-2023 Palomino Solaire 320TSBH travel trailers because these vehicles may be missing the rearward and forward supports for the freshwater tank which may cause the tank to become dislodged - **crash risk**.

United States 03 March 2023: Xos Inc. is recalling 275 units of 2021 RM01, SA01 and 2021-2022 SV05 vehicles because the bolts connecting the electronic parking brake rotor to the driveshaft may have been improperly tightened - **crash risk**.



North America



Recall Summary

United States 03 March 2023: Toyota Motor Engineering & Manufacturing is recalling 130,266 units of 2022-2023 Tundra and Tundra Hybrid vehicles that may be equipped with a Toyota genuine accessory tonneau cover, because the tonneau cover attachment joints may come loose and allow the cover to detach - **crash risk**.

United States 03 March 2023: Lordstown EV Corp. is recalling 7 units of 2023 Endurance vehicles because the electric park brake (EPB) calliper washers may prematurely wear decreasing the clamping performance of the EPB - **crash risk**.

United States 03 March 2023: Dorel Juvenile Group is recalling 59,457 units of Safety 1st onBoard 35 Secure Tech, Safety 1st Secure Tech Infant Base, Maxi-Cosi Coral XP, Maxi-Cosi Mico XP Max, Maxi-Cosi Mico XP, Maxi-Cosi Mico Luxe+ and Maxi-Cosi Infant Base child seats because the lower seat anchors used to secure the child seat base may fail, allowing the child seat to detach - **injury risk**.

Canada 02 March 2023: Newmar is recalling 11 units of 2023 Newmar Bay Star Class A Motorhome, 2023 Bay Star Sport Class A Motorhome and 2012 Canyon Star Class A Motorhome because a problem with the latch for the entry door could cause it to fail - **injury risk**.

Canada 02 March 2023: Land Rover is recalling 82 units of 2023 Land Rover Defender vehicles because the latch that locks the backrest for the third-row seat may not have been manufactured correctly - **injury risk**.

Canada 02 March 2023: Mazda is recalling 2,592 units of 2023 Mazda CX-50 vehicles because a Mazda Genuine Accessory trailer hitch wire harness may have been installed incorrectly - **crash risk**.

United States 02 March 2023: Jaguar Land Rover North America LLC is recalling 812 units of 2023 Land Rover Defender 130 vehicles equipped with third-row seats because the third-row seatback latch may not latch properly, reducing the strength of a child seat installed to the top tether - **injury risk**.

United States 02 March 2023: Winnebago Industries Inc. is recalling 22 units of 2023 Adventurer, Vista and Itasca Sunstar motorhomes because the motorhomes may be

missing the rear reflectors - **crash risk**.

United States 02 March 2023: Off Grid Trailers is recalling 150 units of 2020-2022 Pando, 2020-2023 Expedition and Switchback travel trailers, equipped with certain SDS2 2-Burner Drop-in Cooktops, because the internal aluminium burner tubes that connect to the gas valves may fracture and cause a gas leak - **fire risk**.

United States 02 March 2023: Newmar Corporation is recalling 151 units of 2021-2023 Bay Star, 2023 Bay Star Sport and Canyon Star motorhomes because the entry door latch may fail and not allow entry or exit - **injury risk**.

Canada 01 March 2023: Nissan is recalling 54 units of 2023 Nissan Ariya vehicles because the bolt that attaches the steering wheel may not have been properly tightened or may not have been installed - **crash risk**.

Canada 01 March 2023: Forest River is recalling one 2023 Coachmen Sportscoach motorhome because the latch for the entry door could fail - **injury risk**.

United States 01 March 2023: Airstream Inc. is recalling 6,827 units of 2021-2023 Basecamp, Bambi, Atlas and Interstate travel trailers, equipped with certain SDS2 2-Burner Drop-in Cooktops, because the internal aluminium burner tubes that connect to the gas valves may fracture and cause a gas leak - **fire risk**.

United States 01 March 2023: Forest River Inc. is recalling 19 units of 2013 Coachmen Cross Country and 2023 Coachmen Sportscoach Motorhomes because the entry door latch may fail and not allow entry or exit - **injury risk**.

United States 01 March 2023: Ferrari is recalling 13 units of 2021-2023 Ferrari SF90 Coupe and 2022 SF90 Spider hybrid electric vehicles because when a child seat is installed on the passenger seat, the deployment of the air bag may impact the child seat - **injury risk**.

Contact

Get in touch for support from our global team of Auto Recall Specialists.



auto@securityexchange24.com



+44 (0)1491 683710



www.securityexchange24.com

Emergency

To access emergency support in the event of an incident, call our 24/7 crisis centre.

US: +1 305 384 4825

APAC: +61 2807 30186

UK & EU: +44 20 3284 8844

Training

Security Exchange provides a range of product contamination and recall, tamper and extortion mitigation and response consultancy services for the Contaminated Products Insurance market. In partnering with Salford University Business School, we deliver fully accredited, professional and bespoke industry-based training programmes in food and non-food, automotive, pharmaceutical, consumer goods and environmental management. For further information on these services, please contact us at enquiries@securityexchange24.com.